


The Historical and Architectural
Survey of North Branford

Part D



Prepared by
Totoket Historical Society, Inc.
under the direction of
Frank J. Pannenberg

May 1980

Rel
920.9746
H

Funded by a grant from the Heritage Conservation and
Recreation Service, Department of the Interior, through
the Connecticut Historical Commission and matching in
kind services by the Totoket Historical Society, Inc.

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

FOR OFFICE USE ONLY

Town No.: _____ Site No.: _____

UTM: _____

QUAD: _____

DISTRICT: S NR IF NR SPECIFY Actual Potential

Item # 151

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
 Northford Volunteer Fire Dept. Co. #2

2. TOWN/CITY VILLAGE COUNTY
 North Branford Northford New Haven

3. STREET AND NUMBER (and or location)
 Middletown Ave.

4. OWNER(S)
 Northford Volunteer Fire Dept. Co. #2 Public Private

5. USE (Present) (Historic)
 Fire Department Fire Department

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN
 Yes No Yes No Open for tours

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
 Modern .1964

8. MATERIAL(S) (Indicate use or location when appropriate)
 Clapboard Asbestos Siding Brick veneer front Other (Specify) _____
 Wood Shingle Asphalt Siding Fieldstone
 Board & Batten Stucco Cobblestone
 Aluminum Siding Concrete block cinder block Cut stone Type: _____

9. STRUCTURAL SYSTEM
 Wood frame Post and beam balloon
 Load bearing masonry Structural iron or steel
 Other (Specify) _____

10. ROOF (Type) (Material)
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify) _____
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
 2 (rear) 105' x 40'

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN
 On original site Moved Yes No Addition 2 bay

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify) _____
 Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
 On level land west of road very near village center of Northford. Northford Intermediate School is to rear; Stanley T. Williams School is south.

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

6 bay Fire Station with clean direct lines. No frills, just function.

DESCRIPTION (Continued)

18 ARCHITECT

Matson Drafting, Cheshire

BUILDER

Co. #2-Sub Contracted

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

Fifty men gathered on June 19 & 26, 1944, to organize a volunteer fire company, after a spectacular fire totally destroyed the Congregational Parsonage in Northford. The first fire house, next to the present site, was built in 1946. In 1963 a new and larger pumper, built by Maxim Motor Co. was contracted for. In order to house this new pumper a new building was necessary. To help defray building costs, the First Annual Carnival was held on July 24-27, 1963. On the 25th Anniversary of Co. #2 there was a special parade. The people of the town support the very able work of the Co. #2.

SIGNIFICANCE

SOURCES

Assessor's Office
Co. #2 Captain
Co. #2 Records

PHOTO

PHOTOGRAPHER

Ruth Arnold

VIEW

Front

NEGATIVE ON FILE

COMPILED BY

NAME

Betty J. Henrickson 4/21/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
- Highways
- Vandalism
- Developers
- Other _____
- Renewal
- Private
- Deterloration
- Zoning
- Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

FOR OFFICE USE ONLY

Town No.: _____ Site No.: _____

UTM: | | | | | | | | | | | | | | | | | | | | | |

QUAD: _____

DISTRICT: S NR IF NR SPECIFY Actual Potential

Item # 152

| | | |
|---|---|--|
| IDENTIFICATION | 1. BUILDING NAME (Common) _____ (Historic) _____ | |
| | Northford Intermediate School | |
| | 2 TOWN/CITY _____ VILLAGE _____ COUNTY _____ | |
| | North Branford Northford New Haven | |
| | 3 STREET AND NUMBER (and or location) _____ | |
| | Middletown Ave. | |
| | 4. OWNER(S) _____ <input checked="" type="checkbox"/> Public <input type="checkbox"/> Private | |
| | Town of North Branford | |
| | 5 USE (Present) _____ (Historic) _____ | |
| | School School | |
| DESCRIPTION | 6 ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No EXTERIOR VISIBLE FROM PUBLIC ROAD: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No INTERIOR ACCESSIBLE: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No IF YES, EXPLAIN: School | |
| | 7 STYLE OF BUILDING _____ DATE OF CONSTRUCTION: 1971 | |
| | Modern | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | |
| | <input type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input checked="" type="checkbox"/> Brick veneer <input type="checkbox"/> Other (Specify) _____ <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input type="checkbox"/> Fieldstone <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input checked="" type="checkbox"/> Concrete Type: block <input type="checkbox"/> Cut stone Type: _____ | |
| | 9 STRUCTURAL SYSTEM | |
| | <input type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input type="checkbox"/> balloon <input type="checkbox"/> Load bearing masonry <input checked="" type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____ | |
| | 10 ROOF (Type) | |
| | <input type="checkbox"/> Gable <input checked="" type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ (Material) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Asphalt shingle <input checked="" type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ | |
| | 11 NUMBER OF STORIES: 1 APPROXIMATE DIMENSIONS: 379' x 221' | |
| 12 CONDITION (Structural) _____ (Exterior) _____ | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| 13 INTEGRITY (Location) _____ WHEN? _____ (Alterations) _____ IF YES, EXPLAIN _____ | | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | |
| 14 RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) Open courtyard in center of building <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | |
| 15 SURROUNDING ENVIRONMENT | | |
| <input type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Scattered buildings visible from site <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial <input type="checkbox"/> Rural <input type="checkbox"/> High building density | | |
| 16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| Sited back from road just north of Stanley T. Williams School. Co. #2 Fire Station is on road at front. | | |

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

1. Set back away from main highway.
2. Various building elements capped with heavy cornice bands.
3. Windows are vertically proportioned with small operable awning type windows at base. Predominantly set in groups, the windows are separated by vertical projecting fins extending from near ground to cornice band.
4. Large, free standing, reinforced concrete "Loggia" is situated along front of building with the roof cantilevered from center columns.

18 ARCHITECT

Schilling & Goldbecker

BUILDER

Ames Construction Co.

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

Land purchased from Milton and Mary Stewart - 19.4 acres
and William Haesche - 6.2 acres

SIGNIFICANCE

SOURCES

Superintendent's Office

PHOTO

PHOTOGRAPHER

Ruth Arnold

7/79

VIEW

Front

NEGATIVE ON FILE

yes

COMPILED BY

NAME

Betty J. Henrickson

4/12/80

ORGANIZATION

Totoket Historical Society

ADDRESS

Northford, Conn. 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 154

| | | |
|---|---|-----------|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | |
| | Stanley T. Williams School | |
| | 2 TOWN CITY | VILLAGE |
| | North Branford | Northford |
| | 3 STREET AND NUMBER (and or location) | |
| | Middletown Ave. | |
| | 4. OWNER(S) | |
| | Town of North Branford <input checked="" type="checkbox"/> Public <input type="checkbox"/> Private | |
| | 5. USE (Present) (Historic) | |
| | School | |
| DESCRIPTION | 6. ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | EXTERIOR VISIBLE FROM PUBLIC ROAD <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | INTERIOR ACCESSIBLE <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | IF YES, EXPLAIN School | |
| | 7. STYLE OF BUILDING | |
| | Modern | |
| | DATE OF CONSTRUCTION | |
| | 1961 | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | |
| | <input type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input checked="" type="checkbox"/> Brick Veneer <input type="checkbox"/> Other (Specify) _____ <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input type="checkbox"/> Fieldstone <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input checked="" type="checkbox"/> Concrete Type: <u>block</u> <input type="checkbox"/> Cut stone Type: _____ | |
| 9. STRUCTURAL SYSTEM | | |
| <input type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input type="checkbox"/> balloon <input type="checkbox"/> Load bearing masonry <input checked="" type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____ | | |
| 10. ROOF (Type) | | |
| <input type="checkbox"/> Gable <input checked="" type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ (Material) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Asphalt shingle <input checked="" type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ | | |
| 11. NUMBER OF STORIES | | |
| 1 | | |
| APPROXIMATE DIMENSIONS | | |
| 333' x 130' | | |
| 12. CONDITION (Structural) (Exterior) | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| 13. INTEGRITY (Location) | | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved <input type="checkbox"/> WHEN ? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No IF YES EXPLAIN Right addition-1975, 1980 Back addition | | |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) Tennis courts in front. Flagpole <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | |
| 15. SURROUNDING ENVIRONMENT | | |
| <input type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Scattered buildings visible from site <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Rural <input type="checkbox"/> High building density | | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| On level land set back from road just southwest of Northford Village Center. | | |

(OVER)

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

Steel framed "Loggia" across front.
Long horizontal bands of windows with aluminum mullions in repetitive patterns.
A Nature Trail developed by the Northford Garden Club as an outdoor classroom is in the woods to the rear of the grounds.

SIGNIFICANCE

18 ARCHITECT

Schilling & Goldbecker

BUILDER

W. Pierce Construction Co.

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

Named after Stanley T. Williams (1887-1957) a prominent Northford resident active in many town affairs.

SOURCES

Superintendent's Office

PHOTO

PHOTOGRAPHER

Ruth Arnold

VIEW

Front from south east

NEGATIVE ON FILE

COMPILED BY

NAME


Betty J. Henrickson 4/13/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
- Highways
- Vandalism
- Developers
- Other _____
- Renewal
- Private
- Deterloration
- Zoning
- Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

Item # **154**

| | |
|--|--|
| FOR OFFICE USE ONLY | |
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

IDENTIFICATION

1. BUILDING NAME (Common) _____ (Historic)

2. TOWN/CITY: **North Branford** VILLAGE: **Northford** COUNTY: **New Haven**

3. STREET AND NUMBER (and/or location): **1320 Middletown Ave.**

4. OWNER(S): **Janet L. Armstrong** Public Private

5. USE (Present) _____ (Historic) **Residence** **Residence**

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN _____

DESCRIPTION

7. STYLE OF BUILDING: **Cottage** DATE OF CONSTRUCTION: **c. 1850**

8. MATERIAL(S) (Indicate use or location when appropriate)

Clapboard Asbestos Siding Brick Other (Specify) **small center chimney**

Wood Shingle Asphalt Siding Fieldstone **exterior chimney**

Board & Batten Stucco Cobblestone

Aluminum Siding Concrete Type: **block** Cut stone Type: **sandstone foundation, old part**

9. STRUCTURAL SYSTEM

Wood frame Post and beam balloon

Load bearing masonry Structural iron or steel

Other (Specify) _____

10. ROOF (Type)

Gable Flat Mansard Monitor sawtooth

Gambrel Shed Hip Round Other (Specify) _____

(Material) **on extensions**

Wood Shingle Roll Asphalt Tin Slate

Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES: **1** APPROXIMATE DIMENSIONS: **(Additions (left 13' x 36') 54' x 48' (main 24' x 27') ((right 17' x 30') (Back 16' x 17'))**

12. CONDITION (Structural) _____ (Exterior) _____

Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) _____ WHEN? _____ (Alterations) _____ IF YES, EXPLAIN _____

On original site Moved Yes No **Several additions**

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

Barn Shed Garage Other landscape features or buildings (Specify) **Stable**

Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT

Open land Wood-land Residential Scattered buildings visible from site

Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS

On the west side of Middletown Tpke., gable end to road. Surrounded by garden and open land.

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

Half-moon window in east gable. Low pitched roof. House has either been completely altered by additions or a newer house has been erected on foundation of older one.

18 ARCHITECTURE

BUILDER

Built by/for E. Page

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Used by the late Dr. Armstrong as an optometrist's office as well as residence.

Only one story cottage of the era in town.

SOURCES

Assessor's Office
 County Map 1852) E. Page
 County Map 1856)
 Beers Atlas 1868 - Bela H. Foote

PHOTO
 COMPILED BY

PHOTOGRAPHER

Ruth Arnold

5/79

VIEW

Front-south

NEGATIVE ON FILE

yes

NAME

Betty J. Henrickson

4/1/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117 Northford, CT 06472



21 THREATS TO BUILDING OR SITE

- None known
- Highways
- Vandallism
- Developers
- Other _____
- Renewal
- Private
- Deterloration
- Zoning
- Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

Item # 155

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
St. Monica's Church

2. TOWN CITY VILLAGE COUNTY
North Branford **Northford** **New Haven**

3. STREET AND NUMBER (and or location)
Middletown Ave.

4. OWNER(S) Public Private
St. Monica's Church Corp.

5. USE (Present) (Historic)
Church

6. ACCESSIBILITY TO PUBLIC: Yes No Yes No IF YES, EXPLAIN
Church

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
Neo-Colonial **1951-original, 1978-enlarged**

8. MATERIAL(S) (Indicate use or location when appropriate)
 Clapboard Asbestos Siding Brick Other (Specify) **Tongue and groove diagonal veneer facade/siding at rear of old hall**
 Wood Shingle Asphalt Siding Fieldstone
 Board & Batten Stucco Cobblestone
 Aluminum Siding Concrete Type: **block, poured foundation** Cut stone Type: _____

9. STRUCTURAL SYSTEM **& slabs**
 Wood frame Post and beam balloon
 Load bearing masonry Structural iron or steel
Laminated wood bents supporting 4" double tongue & groove pine roof decking. Wood stud walls with brick exterior veneer.

10. ROOF (Type) (Material)
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify) _____
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
1 **167' x 121' (chapel 57' x 97') (Hall 70' x 48') (orig. bldg. 40' x 76')**

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN
 On original site Moved Yes No **to original building (see #19)**

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify)
107 car paved parking lot.
 Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
East side of Middletown Ave. Close to village. Parking lot and church grounds are bounded on east by the old Northford Cemetery.

(OVER)

DESCRIPTION (Continued)

Gable end to road; small spired cupola near west end. Small stained glass windows at front and sides of main building. Diagonal patterned tongue and groove board surface at rear interior behind altar.

18 ARCHITECT

Arthur D'Olivera

BUILDER

Joseph Calabrese-Waterbury

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

The original St. Monica's Church built in 1951 was constructed with canted, wood sheathed, wing walls like a corner. The new church was built to the south with a connector and the older building rebuilt to conform in design, now used as kitchen and recreation room.

SOURCES

Assessor's records 62-13

PHOTO

PHOTOGRAPHER

Ruth Arnold

11/79

VIEW

3/4 front-S.W.

NEGATIVE ON FILE

yes

COMPILED BY

NAME

Betty J. Henrickson

4/23/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES

HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item #156

IDENTIFICATION

1. BUILDING NAME (Common) _____ (Historic) _____

2. TOWN/CITY: North Branford VILLAGE: Northford COUNTY: New Haven

3. STREET AND NUMBER (and or location): 1059 Middletown Ave.

4. OWNER(S): Anthony & Jane Maisano Public Private

5. USE (Present) _____ (Historic) _____
Residence Residence

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN _____

DESCRIPTION

7. STYLE OF BUILDING: Late Greek Revival DATE OF CONSTRUCTION: c. 1850

8. MATERIAL(S) (Indicate use or location when appropriate):
 Clapboard Asbestos Siding Brick Other (Specify) _____
chimneys (modern 1 on ell)
 Wood Shingle Asphalt Siding Fieldstone
 Board & Batten Stucco Cobblestone
 Aluminum Siding Concrete over Type: _____ Cut stone Type: sandstone foundation

9. STRUCTURAL SYSTEM:
 Wood frame Post and beam balloon
 Load bearing masonry Structural iron or steel
 Other (Specify) _____

10. ROOF (Type):
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify) _____
 (Material)
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES: 2 + attic APPROXIMATE DIMENSIONS: 35' x 28'; wing 18' x 14'

12. CONDITION (Structural): Excellent Good Fair Deteriorated (Exterior) Excellent Good Fair Deteriorated

13. INTEGRITY (Location): On original site Moved WHEN? _____ (Alterations) Yes No IF YES, EXPLAIN: wing altered

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES:
 Barn Shed Garage 2 Other landscape features or buildings (Specify) pond at rear
 Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT:
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Industrial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
East side of Middletown Turnpike between North Haven line and Eight Mile Brook and Hill.

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

Late Greek Revival house with 3 bay front facade and 2 bay end facades, all 6/6 sash including gable windows. Square, chamfered columns on entry porch with bold collared capitals support on entablature with wide cornice and cut away bottom. Wood plinths at base of columns replaced with masonry by present owner. Four panelled front door. Wide, approx. 2', eaves, no brackets or cornice returns. Symmetrical chimneys flanking center bay. Typical center hall, 4 room, plan with stair oriented front to back. Large, turned newel post. Panelled doors.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Unusual construction in this survey area. 16" thick fieldstone walls on sandstone foundation are stuccoed and scored to resemble coursed stone. Several houses of the same period with the same exterior treatment are found in New Haven, On the interior corners, both inner and outer, are rounded. In a 1906 deed the house was referred to as a "certain two story concrete wall house". The land was in the Linsley family from before the 1813 Survey of Middletown Turnpike until 1933. The owner says house was built by a Linsley living across road, in a house now destroyed, for his sister.

SOURCES

N. B. Land Records
 Beers Map 1868
 County Maps 1856 & 1852
 Talk with owner


PHOTOGRAPHER
 Ruth Arnold 4/79

VIEW
 Front NEGATIVE ON FILE
 yes

NAME
 Elizabeth A. Livingston 3/16/80

ORGANIZATION
 Totoket Historical Society, Inc.

ADDRESS
 P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

None known Highways Vandalism Developers Other Large trucking co. to sr th

Renewal Private Deterloration Zoning Explanation

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

FOR OFFICE USE ONLY

Town No.: _____ Site No.: _____

UTM: | | | | | | | | | | | | | | | | | | | | | |

QUAD: _____

DISTRICT: S NR IF NR SPECIFY: Actual Potential

Item # 157

| | | | | |
|--|---|---|---|--|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | | Munson house | |
| | 2 TOWN CITY | VILLAGE | COUNTY | |
| | North Branford | Northford | New Haven | |
| | 3 STREET AND NUMBER (and or location) | | | |
| | 1022 Middletown Ave. | | | |
| | 4 OWNER(S) | | | |
| | Alfred & Ida Guarino <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | | | |
| DESCRIPTION | 5 USE (Present) (Historic) | | Residence | |
| | 6 ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | EXTERIOR VISIBLE FROM PUBLIC ROAD <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
| | 7 STYLE OF BUILDING | | DATE OF CONSTRUCTION | |
| | Contemporary Builders Colonial | | c. 1785 | |
| | 8 MATERIAL(S) (Indicate use or location when appropriate) | | | |
| | <input type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input checked="" type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) _____ <input checked="" type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input type="checkbox"/> Fieldstone <input type="checkbox"/> Cobblestone <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input checked="" type="checkbox"/> Cut stone Type: Brownstone <input type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: _____ | | | |
| | 9 STRUCTURAL SYSTEM | | | |
| | <input checked="" type="checkbox"/> Wood frame <input checked="" type="checkbox"/> Post and beam <input type="checkbox"/> balloon <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Other (Specify) _____ | | | |
| | 10. ROOF (Type) | | | |
| | <input checked="" type="checkbox"/> Gable <input checked="" type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ modern wing (Material) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Other (Specify) _____ <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile | | | |
| 11 NUMBER OF STORIES | | APPROXIMATE DIMENSIONS | | |
| 2 + attic | | 45' x 47' (main 34' x 26') (back wing 24' x 26') | | |
| 12 CONDITION (Structural) | | (Exterior) | | |
| <input checked="" type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | <input checked="" type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| 13 INTEGRITY (Location) | | WHEN ? | (Alterations) IF YES, EXPLAIN | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved | | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Totally rebuilt c. 1959 | |
| 14 RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) Swimming pool Commercial nursery buildings to south. <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | | | |
| 15 SURROUNDING ENVIRONMENT | | | | |
| <input type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input type="checkbox"/> Residential <input checked="" type="checkbox"/> Scattered buildings visible from site <input checked="" type="checkbox"/> Commercial <input checked="" type="checkbox"/> Indus-trial <input type="checkbox"/> Rural <input type="checkbox"/> High building density | | | | |
| 16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | | | |
| West side of road facing east. Nursery business & some open land surround- ing. Trucking/industrial complex across road. About 1/2 mile north of North Haven line. | | | | |

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

Heavily landscaped.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Only reminder of what the simple center chimney house looked like is the original pitch of the roof and small attic gable window (now a louver).
1813 survey of Middletown Turnpike goes to "S. E. corner Jonathan Munson (Capt., 1756-1847) house".

SOURCES

WPA census #6
Samuel Chamberlain photo in "New England Engagement Book, 1947"
Beers Atlas 1868
County Maps 1856, 1852
Assessor 56-18

COMPILED BY PHOTO

PHOTOGRAPHER

Ruth Arnold

4/79

VIEW

3/4 front-N. E.

NEGATIVE ON FILE

yes

NAME

Elizabeth A. Livingston 3/23/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
- Highways
- Vandalism
- Developers
- Other _____
- Renewal
- Private
- Deterioration
- Zoning
- Explanaton _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 158

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
Abijah Hubbard Rogers

2. TOWN/CITY VILLAGE COUNTY
North Branford North Branford (NFD. P.O.) New Haven

3. STREET AND NUMBER (and/or location)
2 Mill Rd.

4. OWNER(S) Public Private
Mario P. & Naomi Tancreti

5. USE (Present) (Historic)
Residence

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
Late Greek Revival c. 1850

8. MATERIAL(S) (Indicate use or location when appropriate)

| | | | |
|---|--|--|--|
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) _____ |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input type="checkbox"/> Fieldstone | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> chimney & foundation | <input type="checkbox"/> Cobblestone |
| <input checked="" type="checkbox"/> Aluminum Siding | <input checked="" type="checkbox"/> Concrete Type: <u>reinfor-</u> | <input type="checkbox"/> Cut stone Type: _____ | |

9. STRUCTURAL SYSTEM cement

| | | |
|--|---|---|
| <input checked="" type="checkbox"/> Wood frame | <input checked="" type="checkbox"/> Post and beam | <input checked="" type="checkbox"/> balloon |
| <input type="checkbox"/> Load bearing masonry | <input type="checkbox"/> Structural iron or steel | |
| <input type="checkbox"/> Other (Specify) _____ | | |

10. ROOF (Type)

| | | | | |
|---|---------------------------------------|----------------------------------|--|--|
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) _____ |
| (Material) | | | | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) _____ | |

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
2 + attic 41' x 36'

12. CONDITION (Structural) asses (Exterior)

| | | | | | | | |
|------------------------------------|-------------------------------|--|---------------------------------------|------------------------------------|--|-------------------------------|---------------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
|------------------------------------|-------------------------------|--|---------------------------------------|------------------------------------|--|-------------------------------|---------------------------------------|

13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN

| | | | | |
|--|--------------------------------|---|-----------------------------|---|
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <u>Completely rebuilt, various wings added.</u> |
|--|--------------------------------|---|-----------------------------|---|

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

| | | | |
|---|-------------------------------|---------------------------------|--|
| <input type="checkbox"/> Barn | <input type="checkbox"/> Shed | <input type="checkbox"/> Garage | <input type="checkbox"/> Other landscape features or buildings (Specify) |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden | |

15. SURROUNDING ENVIRONMENT

| | | | |
|---|---|---|--|
| <input checked="" type="checkbox"/> Open land | <input checked="" type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input type="checkbox"/> Scattered buildings visible from site |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input type="checkbox"/> Rural | <input type="checkbox"/> High building density |

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
On northeast corner of two old town roads - Mill and Totoket. Set back from roads, faces Totoket Rd.

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

1. Wide roof overhangs.
2. 1 original fireplace.
3. Small stomach windows under eaves at front and rear of original part.

House has been so added onto that original part not visible from road. East wing burned some years ago. No doubt built on site of earlier house.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Abijah Rogers succeeded Joe Durren here very early. His great grandson, Abijah Hubbard Rogers (1801-1862), probably built or rebuilt the existing house.*

SOURCES

County Maps 1852-1856
 Beers Atlas 1868
 *Martha Russell's Notes 36-5

PHOTO

PHOTOGRAPHER

Ruth Arnold

11/79

VIEW

3/4 west side

NEGATIVE ON FILE

yes

COMPILED BY

NAME

Helen H. Livingston


3/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM: | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # **159**

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
Newton Robinson

2. TOWN CITY VILLAGE COUNTY
North Branford **North Branford** **New Haven**

3. STREET AND NUMBER (and or location)
9 Mill Road

4. OWNER(S) Public Private
Ralph A. & Irene Cresenzi

5. USE (Present) (Historic)
Residence **Residence**

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN
 Yes No Yes No

7. STYLE OF BUILDING DATE OF CONSTRUCTION
Greek Revival-Italianate **1880**

DESCRIPTION

8. MATERIAL(S) (Indicate use or location when appropriate)

| | | | |
|--|---|--|--|
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) _____ |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input type="checkbox"/> Fieldstone | 3 chimneys (2 modern) & foundation |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: _____ | <input type="checkbox"/> Cut stone Type: _____ | |

9. STRUCTURAL SYSTEM

| | | |
|--|--|---|
| <input checked="" type="checkbox"/> Wood frame | <input type="checkbox"/> Post and beam | <input checked="" type="checkbox"/> balloon |
| <input type="checkbox"/> Load bearing masonry | | <input type="checkbox"/> Structural iron or steel |
| <input type="checkbox"/> Other (Specify) _____ | | |

10. ROOF (Type)

| | | | | |
|---|-------------------------------|----------------------------------|----------------------------------|--|
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) _____ |

(Material)

| | | | |
|---|---------------------------------------|-------------------------------|--|
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) _____ |

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
2 + attic **45' x 45' (main house 20' x 40')**

12. CONDITION (Structural) (Exterior)

| | | | | | | | |
|---|-------------------------------|-------------------------------|---------------------------------------|---|-------------------------------|-------------------------------|---------------------------------------|
| <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
|---|-------------------------------|-------------------------------|---------------------------------------|---|-------------------------------|-------------------------------|---------------------------------------|

13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN
 On original site Moved Yes No **Wing, enclosed porches added.**

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

| | | | |
|---|-------------------------------|---------------------------------|---|
| <input type="checkbox"/> Barn | <input type="checkbox"/> Shed | <input type="checkbox"/> Garage | <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden | picket fence |

15. SURROUNDING ENVIRONMENT

| | | | |
|---|--------------------------------------|---|---|
| <input checked="" type="checkbox"/> Open land | <input type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input type="checkbox"/> Rural | <input type="checkbox"/> High building density |

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
Sited on south side of Mill Rd. on west side of Farm River. House is set close to road. Land slopes gently down to river on east and to rear of house on south.

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

Gable faces the road. Molded cornice with deep returns and wide soffits frames narrow, paired, round headed gable lights. 3 bay facade, 2/2 sash, molded window trim with sills on small brackets. New addition covers entry surround. East gable has triangular headed window. Basically Federal/Greek Revival plan house. Any decorative ornamentation destroyed by additions and residing.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Probably built by/for Newton Robinson.

According to Beers Atlas, there was a blacksmith shop located here c. 1868.

SOURCES

Assessors Records
Beers Atlas 1868
N. B. Land Records 7-227 & 9-162 & 3

PHOTO

PHOTOGRAPHER

Ruth Arnold

6/79

VIEW

Front

NEGATIVE ON FILE

yes

COMPILED BY

NAME

Janet S. Gregan


3/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT. 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

None known Highways Vandalism Developers Other _____

Renewal Private Deterioration Zoning Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|---|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT <input type="checkbox"/> S <input type="checkbox"/> NR | IF NR SPECIFY <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 160

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
 Mill House Roger's Mill

2. TOWN/CITY VILLAGE COUNTY
 North Branford North Branford New Haven

3. STREET AND NUMBER (and/or location)
 16 Mill Rd.

4. OWNER(S) Public Private
 Ronald F. Wipern

5. USE (Present) (Historic)
 Residence Grist mill

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
 Colonial Revival c. 1700-c. 1940

8. MATERIAL(S) (Indicate use or location when appropriate)

| | | | |
|--|--|---|--|
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick chimney | <input type="checkbox"/> Other (Specify) |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input checked="" type="checkbox"/> Fieldstone foundation | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: | <input type="checkbox"/> Cut stone Type: | |

9. STRUCTURAL SYSTEM

| | | |
|--|---|---|
| <input checked="" type="checkbox"/> Wood frame | <input checked="" type="checkbox"/> Post and beam | <input type="checkbox"/> balloon |
| <input type="checkbox"/> Load bearing masonry | | <input type="checkbox"/> Structural iron or steel |
| <input type="checkbox"/> Other (Specify) | | |

10. ROOF (Type)

| | | | | |
|---|---------------------------------------|----------------------------------|--|--|
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) |
| (Material) | | | | |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) | |

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
 1 1/2 40' x 54'

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN
 On original site Moved Yes No Residence-converted from old mill

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify)
dam, mill pond

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
 Sited on dam on west side of Farm River north of Mill Rd.

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

An old structure converted for residential use utilizing colonial forms and details on a casual, comfortable manner. Variety of window types, multi paned sash, casement and large picture window. 3 gable type dormers to east and large shed dormer to west. Stone paved terrace at north overlooks pond.

18 ARCHITECTURE

BUILDER

SIGNIFICANCE

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

"On Farm River at Bare Plain, the Rogers Mills have been operated the best part of 200 years. Samuel A. Rogers was the last of that family to own them. The proprietor since 1880 being Charles Page." (1) Charles Page (1839-1920) was a nephew (?) of Samuel A. Rogers and his adopted son.

SOURCES

1792 Map of Conn. - William Blodget
 County Maps 1852-1856
 Beers Atlas 1868
 (1) History of Conn. Vol IV. Author George B. Chandler - Editor - Harris
 Martha Russell's Notes G. Ostorn.
 Conversation with Mrs. Richard A. Page

PHOTO

PHOTOGRAPHER

Robert Van Nest 1977

VIEW

Side-east

NEGATIVE ON FILE

yes

COMPILED BY

NAME

Janet S. Gegan 3/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

None known Highways Vandalism Developers Other _____

Renewal Private Deterloration Zoning Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR. SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # **161**

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
Star Hill Acre **Ulysses Rogers***

2. TOWN CITY VILLAGE COUNTY
North Branford **North Branford** **New Haven**

3. STREET AND NUMBER (and or location)
26 Mill Rd.

4. OWNER(S)
Frederic W. & Maureen R. Sternberg Public Private

5. USE (Present) (Historic)
Residence **Residence**

6. ACCESSIBILITY TO PUBLIC: Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
Late Federal/Greek Revival **. 1807***

8. MATERIAL(S) (Indicate use or location when appropriate)
 Clapboard Asbestos Siding Brick Other (Specify) **central chimney (rebuilt)**
 Wood Shingle Asphalt Siding Fieldstone **foundation**
 Board & Batten Stucco Cobblestone
 Aluminum Siding Concrete Type: _____ Cut stone Type: _____

9. STRUCTURAL SYSTEM
 Wood frame Post and beam balloon
 Load bearing masonry Structural iron or steel
 Other (Specify) _____

10. ROOF (Type) (Material)
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify) _____
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
2 + attic **44' x 54'**

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN
 On original site Moved Yes No **Additions-interior altered**

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify) **Swimming pool-Brick & flagstone terraces**
 Carriage house Shop Garden **Wood deck-Gazebo-Cabanas**

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
Sited on north side of Mill Rd. just east of dam & mill-pond. House is raised from road level on slight hill surrounded by mature trees and attractively landscaped.

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

1. Across Mill Road from the house is a very large ancient white oak tree which might date from the early 18th century lotment surveys.
2. Much added to over the years.
3. Shallow pitched roofs of moderate overhang with no returns. Gable end faces street, 3 windows first floor, 2 windows second, 6/6 windows.
4. Delicate door surround at front with slightly raised pilasters supporting an entablature under which is a row of dentils. At east side is a hip roofed porch running length of house supported on plain doric columns.
5. Addition to south has chestnut sliding from old barn.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Uriah Robinson operated a saw mill here.
 Third District School got its water supply from this house.
 Another possible date for this house is c. 1820, by Samuel A. Rogers.

SOURCES

County Maps 1852-1856
 Beers Atlas 1868
 N. B. Land Records 4-39
 *Owner, Mrs. Frederic Sternberg

PHOTO

PHOTOGRAPHER

Ruth Arnold

5/79

VIEW

3/4 Left front

NEGATIVE ON FILE

yes

COMPILED BY

NAME

Janet S. Gregan

3/15/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item #162

| | | | | |
|--|--|------------------------|---|-----------|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | | Edmund Field | |
| | 2. TOWN CITY | | VILLAGE | COUNTY |
| | North Branford | | North Branford | New Haven |
| | 3. STREET AND NUMBER (and or location) | | | |
| | 34 Mill Rd. | | | |
| | 4. OWNER(S) | | | |
| Charles E. & Victoria Strickland <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | | | | |
| DESCRIPTION | 5. USE (Present) | | (Historic) | |
| | Residence | | Residence | |
| | 6. ACCESSIBILITY TO PUBLIC: | | IF YES, EXPLAIN | |
| | EXTERIOR VISIBLE FROM PUBLIC ROAD | | INTERIOR ACCESSIBLE | |
| | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
| | 7. STYLE OF BUILDING | | | |
| | Late Greek Revival-Victorian | | DATE OF CONSTRUCTION | |
| | | | 1880-81 | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | | | |
| | <input checked="" type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input checked="" type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) chimney (modern) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input checked="" type="checkbox"/> Fieldstone foundation <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: <input type="checkbox"/> Cut stone Type: | | | |
| 9. STRUCTURAL SYSTEM | | | | |
| <input checked="" type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input checked="" type="checkbox"/> balloon <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) | | | | |
| 10. ROOF (Type) | | | | |
| <input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) (Material) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) | | | | |
| 11. NUMBER OF STORIES | | APPROXIMATE DIMENSIONS | | |
| 2 + attic | | 33' x 54' (main house) | | |
| 12. CONDITION (Structural) (Exterior) | | | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | | | |
| 13. INTEGRITY (Location) | | WHEN ? | (Alterations) | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved | | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | | Remodeled 1957 | | |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | | | |
| <input checked="" type="checkbox"/> Barn <input type="checkbox"/> Shed <input checked="" type="checkbox"/> Garage <input type="checkbox"/> Other landscape features or buildings (Specify) concrete block <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | | | |
| 15. SURROUNDING ENVIRONMENT | | | | |
| <input checked="" type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input checked="" type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial <input type="checkbox"/> Rural <input type="checkbox"/> High building density | | | | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | | | |
| House sited on slight hill, north side of Mill Rd. To east is old Third District School, now a residence. To west is old Rogers house & mill pond. | | | | |

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

One round headed window on second story, west side. Window inset on corner of the wing with curved brace canopy in the Queen Anne style. Moderately large roof overhangs, no returns.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Edmund Field (1851-1920) bought 45 rods from Charles Page on Aug. 13, 1880 and built this house. He married Harriet Page, Charles' daughter, April 1879.

SOURCES

Assessor's Records
N. B. Land Records 8-60
Martha Russell's Notes, pg. 37-7

PHOTO

PHOTOGRAPHER

Ruth Arnold

5/79

VIEW

Front

NEGATIVE ON FILM

yes

COMPILED BY

NAME

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| | |
|--|--|
| FOR OFFICE USE ONLY | |
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 263

| | | | | |
|---|---|------------------------|---|--|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | | 3 rd District School | |
| | 2. TOWN CITY | VILLAGE | COUNTY | |
| | North Branford | North Branford | New Haven | |
| | 3. STREET AND NUMBER (and or location) | | | |
| | 44 Mill Rd. | | | |
| | 4. OWNER(S) | | | |
| | Charles E. Strickland <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | | | |
| | 5. USE (Present) | | (Historic) | |
| | Residence | | School | |
| | 6. ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No IF YES, EXPLAIN | | | |
| 7. STYLE OF BUILDING | | | DATE OF CONSTRUCTION | |
| Late Greek Revival | | | c. 1850 | |
| 8. MATERIAL(S) (Indicate use or location when appropriate) | | | | |
| <input type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) _____ <input checked="" type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input checked="" type="checkbox"/> Fieldstone foundation, faced in front with concrete <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: _____ <input type="checkbox"/> Cut stone Type: _____ | | | | |
| 9. STRUCTURAL SYSTEM | | | | |
| <input checked="" type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input checked="" type="checkbox"/> balloon <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Other (Specify) _____ | | | | |
| 10. ROOF (Type) | | | | |
| <input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ (Material) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ | | | | |
| 11. NUMBER OF STORIES | | APPROXIMATE DIMENSIONS | | |
| 1 + attic | | 20' x 45' | | |
| 12. CONDITION (Structural) (Exterior) | | | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | | | |
| 13. INTEGRITY (Location) | | WHEN ? | (Alterations) IF YES, EXPLAIN | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved | | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Converted to residence & enlarged | |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage <input type="checkbox"/> Other landscape features or buildings (Specify) _____ <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | | | |
| 15. SURROUNDING ENVIRONMENT | | | | |
| <input checked="" type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input checked="" type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Rural <input checked="" type="checkbox"/> High building density | | | | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | | | |
| Building sited on slight hill, north side of Mill Rd. near Farm River. Surrounded on east and north by housing developments. | | | | |

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

Wide roof overhangs, no returns. Entry porch has matching roof slope and overhangs. Small, rectangular gable light with 3 panes at front. Shed addition and brick chimney at rear. 6/6 windows.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

The Third District School, sometimes called the school at Bare Plain, was established prior to 1763 according to a Second Society vote, March 13, 1763, concerning payment of equal proportion of school moneys. The present building is of mid-19th century construction.

SOURCES

County Maps 1852-1856
Beers Atlas 1868
Records of Second and North Society, Book 2nd 1731

PHOTO

PHOTOGRAPHER

Ruth Arnold

5/79

VIEW

Front

NEGATIVE ON FILM

yes

COMPILED BY

NAME

Janet S. Gregan


3/20/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanaton _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| | |
|--|--|
| FOR OFFICE USE ONLY | |
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR. SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # **164**

IDENTIFICATION

| | |
|--|---|
| 1. BUILDING NAME (Common) (Historic) | |
| Charles Page | |
| 2 TOWN/CITY | VILLAGE COUNTY |
| North Branford | North Branford(Nfd. P.O.) New Haven |
| 3 STREET AND NUMBER (and/or location) | |
| Mill Rd. | |
| 4. OWNER(S) <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | |
| Henry & Jane Forte | |
| 5. USE (Present) (Historic) | |
| Residence Residence | |
| 6. ACCESSIBILITY TO PUBLIC: | EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |

DESCRIPTION

| | | |
|--|---|--|
| 7. STYLE OF BUILDING | | DATE OF CONSTRUCTION |
| Greek Revival/Italianate | | 1871 |
| 8. MATERIAL(S) (Indicate use or location when appropriate) | | |
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Shingles | <input checked="" type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input checked="" type="checkbox"/> Fieldstone |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: _____ | <input type="checkbox"/> Cut stone Type: _____ |
| 9. STRUCTURAL SYSTEM | | |
| <input checked="" type="checkbox"/> Wood frame | <input type="checkbox"/> Post and beam | <input type="checkbox"/> balloon |
| <input type="checkbox"/> Load bearing masonry | <input type="checkbox"/> Structural iron or steel | |
| <input type="checkbox"/> Other (Specify) _____ | | |
| 10. ROOF (Type) | | |
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile |
| <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth | <input type="checkbox"/> Round |
| <input type="checkbox"/> Other (Specify) _____ | | |
| 11. NUMBER OF STORIES APPROXIMATE DIMENSIONS | | |
| 2 + attic | 27' x 58' (Main house 22' x 28') | |
| 12. CONDITION (Structural) (Exterior) | | |
| <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair |
| <input type="checkbox"/> Deteriorated | <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good |
| <input type="checkbox"/> Fair | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
| 13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN | | |
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input type="checkbox"/> Barn | <input checked="" type="checkbox"/> Shed | <input checked="" type="checkbox"/> Garage |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden |
| <input type="checkbox"/> Other landscape features or buildings (Specify) _____ | | |
| 15. SURROUNDING ENVIRONMENT | | |
| <input checked="" type="checkbox"/> Open land | <input type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input type="checkbox"/> Rural |
| <input type="checkbox"/> High building density | <input checked="" type="checkbox"/> Scattered buildings visible from site | |

| |
|---|
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS |
| Sited on top of slight hill, south side of Mill Rd. on large acreage. |

(OVER)

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

Gable end to road with wide cornices and deep returns. Italianate door and side porch with square collared pilasters and columns. Three bay facade; side-hall plan. Gable light was probably originally round headed. Two additions at rear center on gable end of main house and step down in interesting manner.

18 ARCHITECT

BUILDER

SIGNIFICANCE

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

1. Built by/for Deacon Charles Page (1839-1920). He was the son of Benjamin & Sara Page and adopted son of Samuel A. Rogers. He took over Rogers Mill in 1880. He was also a deacon of the Congregational Church and Town Clerk. The Town Clerk's office was in this house.
2. There was an older house just to east built by Thomas Rogers, grandfather of Samuel A. Rogers.

SOURCES

County Maps 1852-1856
 Beers Atlas 1868
 Assessors Records
 Martha Russell's Notes
 Gordon Miller's Study of Northford-North Branford Industrial Revolution Sites
 Cemetery Records

PHOTOGRAPHER
 Ruth Arnold 5/79

VIEW
 Front NEGATIVE ON FILE
 yes

COMPILED BY
 NAME
 Janet S. Gegan 2/80

ORGANIZATION
 Totoket Historical Society, Inc.

ADDRESS
 P. O. Box 117, Northford, Ct 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

None known Highways Vandalism Developers Other _____

Renewal Private Deterioration Zoning Explanation _____

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item #165

IDENTIFICATION

1. BUILDING NAME (Common) *(Historic)* Samuel Factor Russell

2. TOWN CITY North Branford VILLAGE (Nfd. P. O.) North Branford COUNTY New Haven

3. STREET AND NUMBER (and or location) 110 Mill Rd.

4. OWNER(S) Mrs. Fred Augur (Margaret) Public Private

5. USE (Present) *(Historic)* Residence

6. ACCESSIBILITY TO PUBLIC: Yes No EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN

DESCRIPTION

7. STYLE OF BUILDING Greek Revival DATE OF CONSTRUCTION c. 1833

8. MATERIAL(S) (Indicate use or location when appropriate)

| | | | |
|---|---|---|--|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) _____ |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input type="checkbox"/> Fieldstone | 2 chimneys |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: _____ | <input checked="" type="checkbox"/> Cut stone Type: sandstone | |

9. STRUCTURAL SYSTEM

| | | |
|--|---|----------------------------------|
| <input checked="" type="checkbox"/> Wood frame | <input checked="" type="checkbox"/> Post and beam | <input type="checkbox"/> balloon |
| <input type="checkbox"/> Load bearing masonry | <input type="checkbox"/> Structural iron or steel | |
| <input type="checkbox"/> Other (Specify) _____ | | |

10. ROOF (Type)

| | | | | |
|---|---|----------------------------------|--|--|
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input checked="" type="checkbox"/> Shed rear | <input type="checkbox"/> Hip | <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) _____ |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) _____ | |

11. NUMBER OF STORIES 1 1/2 APPROXIMATE DIMENSIONS 44' x 36' (22' x 30') wing (30' x 18')

12. CONDITION (Structural) *(Exterior)*

| | | | | | | | |
|------------------------------------|--|-------------------------------|---------------------------------------|------------------------------------|--|-------------------------------|---------------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
|------------------------------------|--|-------------------------------|---------------------------------------|------------------------------------|--|-------------------------------|---------------------------------------|

13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN

| | | | | |
|--|--------------------------------|---|-----------------------------|---|
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | E11 early addition c. 1850, then extend |
|--|--------------------------------|---|-----------------------------|---|

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

| | | | |
|---|-------------------------------|---------------------------------|--|
| <input type="checkbox"/> Barn | <input type="checkbox"/> Shed | <input type="checkbox"/> Garage | <input type="checkbox"/> Other landscape features or buildings (Specify) |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden | |

15. SURROUNDING ENVIRONMENT

| | | | |
|---|--------------------------------------|---|---|
| <input checked="" type="checkbox"/> Open land | <input type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input checked="" type="checkbox"/> Rural | <input type="checkbox"/> High building density |

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS

Sited on North side of Mill Rd. on slight rise above surrounding open level farm fields.

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

Exterior: Gable end to road with rather low-pitched roof. Fairly deep cornice on front gable (with short returns). Flush rakes on north gable. Doorway typically Greek Revival with flat pilasters & entablature, but no sidelights. Ell is probably an early addition with 1/2 size windows on 2nd floor (butting of the two parts of the house unlikely to be original construction). Front windows 6/6 downstairs: unbalanced sash upstairs probably originally 8/12. Center chimneys in main house and (rebuilt) in ell.

SIGNIFICANCE

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

1. By/for Samuel Factor Russell (1803-1888) who married Anna Chidsey (1807-1835) in 1832.
2. It was built on site of earlier house built by Nehemiah Rogers who sold to Abiather Camp. Abiather Camp was a Tory who went to Nova Scotia during War of 1776 and the farm was confiscated by the government.*

SOURCES

County Maps 1852-1863
Beers Atlas 1868
*Martha Russell's Notes 38-11
Cemetery Records

PHOTO
COMPILED BY

| | | |
|--------------|------------------------------------|-------------------------|
| PHOTOGRAPHER | Ruth Arnold | 5/79 |
| VIEW | Front | NEGATIVE ON FILE yes |
| NAME | Janet S. Grogan | 3/80 |
| ORGANIZATION | Totoket Historical Society, Inc. | |
| ADDRESS | P. O. Box 117, Northford, CT 06472 | |



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

| | | | | |
|---|-----------------------------------|--|-------------------------------------|--|
| <input checked="" type="checkbox"/> None known. | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Other _____ |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Zoning | <input type="checkbox"/> Explanation _____ |

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| | |
|--|--|
| FOR OFFICE USE ONLY | |
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 166

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
Daniel Page

2. TOWN, CITY VILLAGE COUNTY
North Branford North Branford New Haven

3. STREET AND NUMBER (and/or location)
165 Mill Rd.

4. OWNER(S)
Leonard W. Labaree Public Private

5. USE (Present) (Historic)
Residence Residence

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN
 Yes No Yes No

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
Colonial 1778

8. MATERIAL(S) (Indicate use or location when appropriate)
 Clapboard Asbestos Siding Brick Other (Specify)
center chimney (& 1 modern for furnace)
 Wood Shingle Asphalt Siding Fieldstone foundation
 Board & Batten Stucco Cobblestone
 Aluminum Siding Concrete Type: _____ Cut stone Type: _____

9. STRUCTURAL SYSTEM
 Wood frame Post and beam balloon
 Load bearing masonry Structural iron or steel
 Other (Specify) _____

10. ROOF (Type)
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify) _____
 (Material)
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
2 + attic 38' EW x 53' NS

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN
 On original site Moved Yes No wing added early

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed 2 Garage Other landscape features or buildings (Specify)
 Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Industrial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
House on south side of Mill Rd. on level plot. Directly to rear are the athletic fields of the High School.

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

Exterior: Five-bay facade. Square headed Palladian window (central sash 3 panes wide, sidelights 2). 12/12 sash throughout house. Front door has narrow panelled pilasters with simple molded head. Double leaf flush paneled doors with oval bull's eye glass set diagonally in upper panels. Unusual cornice of delicate moldings and a band of thin sawed pieces applied to a flat surface. Well defined drip courses at top of chimney. Two 6/6 windows in attic gables.
Interior: Two fireplaces have elaborate mantels. The front rooms have chair rails; that in the west room has molding applied in an alternating diagonal pattern. These decorations may have been added by Daniel son Benjamin on his marriage in 1798.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Built by/for Daniel Page (1722-1779) (1)
 "Mr. Page was a person of great intelligence and sound judgement. His townsmen sent him to the General Court from the year 1750 to the time of his death in 1779" (2)

SOURCES

County Map 1852-1856
 Beers Atlas 1868
 Assessor's Records
 (2) Martha Russell's Notes 39-12
 WPA Census #32
 Augur Genealogy Map

(1) Owner's research in Land & Probate Records.

PHOTO

PHOTOGRAPHER

Robert Van Nest

1977

VIEW

3/4 Left front

NEGATIVE ON FILM

yes

COMPILED BY

NAME

Elizabeth A. Livingston

3/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known Highways Vandalism Developers Other _____
 Renewal Private Deterioration Zoning Explanation _____

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford, Connecticut 06106

HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

CONTINUATION SHEET

Item number: 167 Date: _____

Control Buildings:

1. "Gulth" Intake 1^S brick 20' X 25'
2. Round Hill 1^S " 10' X 14'
3. Little Gulth 1^S " 10' X 14'
4. Lumpak 1^S " 9' X 11'
5. Farm River Diversion 1^S brick 14' X 20'.
6. North St. Control 1^S brick 14' X 14'.
7. "Blow Off" Control 1^S brick 12' X 14'.

Boat House: 2^S frame 30' X 30'.

Garage 1^S frame w/loft 14' X 18'.

Tool Shed 1^S frame 12' X 20' & 5' X 6'.

Outhouses - 2 1^S frame 4' X 4'.

Intake House 1^S brick 31' X 33' & 8' X 10' - Built 1929
65' high (base to roof) 1 foot thick.
Controls water flow to treatment plant.

Bridge 8' X 14' Concrete
8' X 100' Steel

6 Spillways

Item number: 17

The Great Hill Tunnel, 1933, carries water out of reservoir.

Deepest point of reservoir is opposite the Great Hill Tunnel intake at the southwest shore where Goshen Pond used to be - over 100'. Average depth across lower third of reservoir is 60'.

The island at center is 40 acres in area. There appears to be the remains of a sandstone quarry at the north end of the island, visible at very low water. It is believed that the sandstone used for foundations in the area and probably the Northford Congregational Church was quarried here.

FOR OFFICE USE ONLY

TOWN NO.: _____ SITE NO.: _____
UTM: 18/____/____/____/____/____
QUAD:
DISTRICT: S NR: ACTUAL
POTENTIAL

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| | |
|--|--|
| FOR OFFICE USE ONLY | |
| Town No.: | Site No. |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item #167

| | | |
|---|---|---|
| IDENTIFICATION | 1. BUILDING NAME (Common) Name (Historic) | |
| | Lake Gaillard Dam & Reservoir | |
| | 2 TOWN CITY | VILLAGE |
| | North Branford | North Branford |
| | 3 STREET AND NUMBER (and or location) | |
| | End of North St. & Great Hill Rd. | |
| | 4. OWNER(S) | |
| New Haven Water Company <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | | |
| DESCRIPTION | 5 USE (Present) (Historic) | |
| | Water supply for Metropolitan N.H. farm lands | |
| | 6 ACCESSIBILITY TO PUBLIC: | EXTERIOR VISIBLE FROM PUBLIC ROAD |
| | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| | 7. STYLE OF BUILDING | |
| | DATE OF CONSTRUCTION | |
| | 1925 to 1933 | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | |
| | <input type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) _____ <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input type="checkbox"/> Fieldstone <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input checked="" type="checkbox"/> Concrete Reinforced concrete dams & spillways Type: _____ <input type="checkbox"/> Cut stone Type: _____ | |
| | 9 STRUCTURAL SYSTEM | |
| <input type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input type="checkbox"/> balloon <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____ | | |
| 10 ROOF (Type) | | |
| <input type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ (Material) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ | | |
| 11 NUMBER OF STORIES | | |
| APPROXIMATE DIMENSIONS | | |
| Dam 1024' long; 11' top - 50' base | | |
| 12 CONDITION (Structural) (Exterior) | | |
| <input checked="" type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input checked="" type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| 13 INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN | | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved <input type="checkbox"/> Yes <input type="checkbox"/> No | | |
| 14 RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage <input checked="" type="checkbox"/> Other landscape features or buildings. (Specify) See continuation sheet <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | |
| 15 SURROUNDING ENVIRONMENT | | |
| <input checked="" type="checkbox"/> Open land <input checked="" type="checkbox"/> Wood-land <input type="checkbox"/> Residential <input type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial <input checked="" type="checkbox"/> Rural <input type="checkbox"/> High building density | | |
| 16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| Dam forms Lake Gaillard which is surrounded by wooded hills. No development visible. | | |

(OVER)

DESCRIPTION (Continued)

Total area of reservoir - 1,115 acres.
 Storage capacity when full - 15,642,000,000 gallons.
 7.63 sq. mi. of watershed naturally tributary to reservoir.
 Additional 31.1 sq. mi. of watershed brought into effect by the Sugarloaf Tunnel, 3 miles, to Menuckatuck Reservoir in North Guilford and the Gulf Tunnel to Gulf Brook and other tributaries on the west side of Totoket Mountain (Northford diversions). These tunnels were built at the time of the original reservoir construction - 1933. A later tunnel - 1950's -, the Genesee Tunnel, connects the Menuckatuck Reservoir to Lake Hammonasset at the Killingworth-Madison line.
 (see continuation sheet)

18 ARCHITECT

Albert B. Hill - Engineer

BUILDER

C. W. Blakeslee & Sons

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

New Haven Water Company after much study decided that the natural land basin in North Branford bounded west by Great Hill or Totoket Mountain and on the east by Sea Hill could be dammed to form a reservoir. They started acquiring land in 1923. In 1925 construction began on the dam and finished in 1933.

The area Lake Gaillard and its surrounding watershed area covered once held 22 residences and farms.

Two panelled rooms from the Rose House are installed in the Yale University Art Gallery.

1/3 of the town is now Water Company property

SOURCES

Assessor's records - 38.
 Interview with Clifford Harrison.
 " " Otto Schaefer

PHOTO

PHOTOGRAPHER

Ruth Arnold 11/1979

VIEW

Dam - looking northeast

NEGATIVE ON

COMPILED BY

NAME


Janet Gregan 3/1980

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P.O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known Highways Vandalism Developers Other _____
 Renewal Private Deterioration Zoning Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| | |
|--|--|
| FOR OFFICE USE ONLY | |
| Town No.: | Site No.: |
| UTM: | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # **168**

| | | |
|---|--|--|
| IDENTIFICATION | 1. BUILDING NAME (Common) Harrison's (Historic) Dr. Sheldon Beardslev | |
| | 2. TOWN/CITY North Branford | VILLAGE North Pranford COUNTY New Haven |
| | 3. STREET AND NUMBER (and/or location) North Street (last house on east of North St. before Dam) | |
| | 4. OWNER(S) Harrison, Mrs. Frederick and Clifford <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | |
| | 5. USE (Present) 2 family residence (Historic) Residence | |
| | 6. ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | EXTERIOR VISIBLE FROM PUBLIC ROAD <input type="checkbox"/> Yes <input type="checkbox"/> No INTERIOR ACCESSIBLE <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No IF YES, EXPLAIN |
| | 7. STYLE OF BUILDING Italianate DATE OF CONSTRUCTION 1840 | |
| DESCRIPTION | 8. MATERIAL(S) (Indicate use or location when appropriate) | |
| | <input checked="" type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) _____ | |
| | <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input type="checkbox"/> Fieldstone | |
| | <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone | |
| | <input type="checkbox"/> Aluminum Siding <input checked="" type="checkbox"/> Concrete foundation of addition <input checked="" type="checkbox"/> Cut stone Type: sandstone foundation | |
| | 9. STRUCTURAL SYSTEM | |
| | <input checked="" type="checkbox"/> Wood frame <input checked="" type="checkbox"/> Post and beam <input type="checkbox"/> balloon | |
| | <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel | |
| | <input type="checkbox"/> Other (Specify) _____ | |
| | 10. ROOF (Type) | |
| <input type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth | | |
| <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input checked="" type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ | | |
| <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate | | |
| <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ | | |
| 11. NUMBER OF STORIES 2 APPROXIMATE DIMENSIONS 70' X 40' | | |
| 12. CONDITION (Structural) <input checked="" type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated (Exterior) <input checked="" type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| 13. INTEGRITY (Location) <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved WHEN? (Alterations) <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No IF YES, EXPLAIN 3 additions & conversion to a 2-family home. Has lost all of its original detailing on exterior. | | |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input checked="" type="checkbox"/> Barn <input checked="" type="checkbox"/> Shed <input type="checkbox"/> Garage <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) Sugar house | | |
| <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | |
| 15. SURROUNDING ENVIRONMENT | | |
| <input checked="" type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input checked="" type="checkbox"/> Scattered buildings visible from site | | |
| <input type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial <input type="checkbox"/> Rural <input type="checkbox"/> High building density | | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| Part of farm which has been divided into several house sites. Surrounded by New Haven Water Company property and access to Lake Gaillard Dam. | | |

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

- 1) Very little of original house remains except exterior walls, and these were altered with new siding and new window locations in 1926.
- 2) 6/1 sash windows.
- 3) Roof overhangs original on main house.

18 ARCHITECT

BUILDER

Jasper Munroe

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

- 1) Built by Jasper Munroe who sold to Dr. Sheldon Beardsley. It had several changes of ownership until the Harrisons bought it from the Barthomews in 1926 when Lake Gaillard Dam was built and the Harrison's house was covered by lake. It was converted at that time to a two family residence. The Harrison's have a lifetime right to tap maple trees on Water Company property for sap. They make maple sugar in an old sugar house on property.
- 2) House is near site of older house owned by an earlier settler called Brockway. Nearby was a place where potash was manufactured in early times, and in early 1800's, a distillery was erected there for the making of cider brandy. It was run only a short time.*

SOURCES

County Maps 1852-1856 - Beers Map 1868

*Martha Russell's Notes relating to Early Settlers on North Pranford
Talk with Mrs. Frederick Harrison - co-owner.

PHOTO

PHOTOGRAPHER

Ruth Arnold

4/79

VIEW

South - right side

NEGATIVE ON FILE

Yes

COMPILED BY

NAME

Janet Gegan

6/79

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P.O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # **169**

| | | | | |
|---|---|--|--|---|
| IDENTIFICATION | 1. BUILDING NAME (Common) | | (Historic) | |
| | - | | Nathan Harrison | |
| | 2 TOWN CITY | VILLAGE | COUNTY | |
| | North Branford | North Branford | New Haven | |
| | 3 STREET AND NUMBER (and or location) | | | |
| | 87 North Street | | | |
| | 4. OWNER(S) | | | |
| | Albert and Christine Harrison | | | |
| | | | <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private |
| | 5. USE (Present) | | (Historic) | |
| Residence | | Residence | | |
| 6. ACCESSIBILITY TO PUBLIC: | EXTERIOR VISIBLE FROM PUBLIC ROAD | INTERIOR ACCESSIBLE | IF YES, EXPLAIN | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | | |
| 7. STYLE OF BUILDING | | | DATE OF CONSTRUCTION | |
| Bungalow | | | 1926-27 | |
| 8. MATERIAL(S) (Indicate use or location when appropriate) | | | | |
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) | |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input type="checkbox"/> Fieldstone | | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | | |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: | <input checked="" type="checkbox"/> Cut stone Type: sardstone - foundation | | |
| 9. STRUCTURAL SYSTEM | | | | |
| <input checked="" type="checkbox"/> Wood frame | <input type="checkbox"/> Post and beam | <input checked="" type="checkbox"/> balloon | | |
| <input type="checkbox"/> Load bearing masonry | | <input type="checkbox"/> Structural iron or steel | | |
| <input type="checkbox"/> Other (Specify) | | | | |
| 10. ROOF (Type) | | | | |
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) | |
| (Material) | | | | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) | |
| 11. NUMBER OF STORIES | | APPROXIMATE DIMENSIONS | | |
| 2 + attic | | 38' X 26' | | |
| 12. CONDITION (Structural) | | | | |
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | |
| | | <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | |
| 13. INTEGRITY (Location) | | | | |
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | WHEN ? | (Alterations) <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | | | |
| <input type="checkbox"/> Barn | <input type="checkbox"/> Shed | <input checked="" type="checkbox"/> Garage | <input type="checkbox"/> Other landscape features or buildings (Specify) | |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden | | |
| 15. SURROUNDING ENVIRONMENT | | | | |
| <input checked="" type="checkbox"/> Open land | <input type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site | |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Industrial | <input type="checkbox"/> Rural | <input type="checkbox"/> High building density | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | | | |
| Built on plot that is part of original farm (see #). House is located on paved private road on east side of North Street. Four other houses and scattered outbuildings occupy original farm lot. | | | | |

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

- 1) Woodshed attached to rear of house covers the well that served the entire farm when house was built. That included three houses and cowbarn.
- 2) Foundation stone is from the old house foundations of the homes covered by Lake Gaillard.

18 ARCHITECTY


BUILDER

Harrison Brothers

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

- 1) The garage housed the first fire engine in North Branford, 1938-1952.
- 2) Garage also housed a mechanic's shop.



SOURCES

Town Assessor's Office.
 Talk with Mrs. Albert Harrison, owner.
 Talk with Mrs. Durton Hall, daughter of Floyd Griswold who built the house next door and Totoket Historical Society researcher.
 Talk with fire chief, Andrew Amatrudo.

PHOTO

PHOTOGRAPHER

Ruth Arnold

3/79

VIEW

House - front, garage-rt. front yes

NEGATIVE ON FILE

COMPILED BY

NAME

Janet S. Gegan

7/11/79

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P.O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # **170**

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
Floyd Griswold

2. TOWN/CITY VILLAGE COUNTY
North Branford North Branford New Haven

3. STREET AND NUMBER (and/or location)
83 North St.

4. OWNER(S)
Rose Colletta Public Private

5. USE (Present) (Historic)
Residence Residence

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN
 Yes No Yes No

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
Bungalow 1927

8. MATERIAL(S) (Indicate use or location when appropriate)
 Clapboard Asbestos Siding Brick Other (Specify) _____
 Wood Shingle Asphalt Siding Fieldstone
 Board & Batten Stucco Cobblestone
 Aluminum Siding Concrete Type: _____ Cut stone Type: _____

9. STRUCTURAL SYSTEM
 Wood frame Post and beam balloon
 Load bearing masonry Structural iron or steel
 Other (Specify) _____

10. ROOF (Type) (Material)
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify) _____
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
2 50' x 28'

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) (Alterations) WHEN? IF YES, EXPLAIN
 On original site Moved Yes No **Dormer added, made into 2 family residence-1940**

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify) _____
 Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
Sited on private drive off North St. on east side facing west. It is on part of the Harrison Farm. This house is part of an architecturally related building cluster which might be a potential historic district. (OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

A very broad bungalow with low pitched roof, almost in "summer cottage" style. Room, now glazed in, over front portico, was added 1940. Wide cornice, with returns, all around. Three-sided bay window on south side. Paired windows (6/6) in gables and on ground floor.

18 ARCHITECT

BUILDER

Samuel Taylor

Nathan Harrison

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

On Harrison farm, - one of houses built because owners were displaced when Water Company constructed Lake Gaillard.

SOURCES

Assessor's Record 26-24
Former owner's daughter, Mrs. Edna Hall

PHOTO

PHOTOGRAPHER

Ruth Arnold

4/79

VIEW

Front

NEGATIVE ON FILE

yes

COMPILED BY

NAME


Janet S. Grogan

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No. |
| UTM: | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 171

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
 Seth Russell House Seth Russell

2. TOWN CITY VILLAGE COUNTY
 North Branford North Branford New Haven

3. STREET AND NUMBER (and or location)
 60 North St.

4. OWNER(S)
 Douglas B. Holabird Public Private

5. USE (Present) (Historic)
 Residence Residence

6. ACCESSIBILITY TO PUBLIC: Yes No Yes No IF YES, EXPLAIN

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
 Italianate 1845

8. MATERIAL(S) (Indicate use or location when appropriate)

| | | | |
|--|---|--|--|
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) _____ |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input checked="" type="checkbox"/> Fieldstone | chimneys-2 |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | foundation-both additions |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: _____ | <input checked="" type="checkbox"/> Cut stone Type: sandstone-original house | |

9. STRUCTURAL SYSTEM

| | | |
|--|---|---|
| <input checked="" type="checkbox"/> Wood frame | <input type="checkbox"/> Post and beam | <input checked="" type="checkbox"/> balloon |
| <input type="checkbox"/> Load bearing masonry | <input type="checkbox"/> Structural iron or steel | |
| <input type="checkbox"/> Other (Specify) _____ | | |

10. ROOF (Type)

| | | | | |
|---|--|--|--|--|
| <input checked="" type="checkbox"/> Gable additions | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input checked="" type="checkbox"/> Hip main | <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) _____ |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll. Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) _____ | |

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
 2 35' x 58'

12. CONDITION (Structural) (Exterior)

| | | | | | | | |
|---|-------------------------------|-------------------------------|---------------------------------------|------------------------------------|--|-------------------------------|---------------------------------------|
| <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
|---|-------------------------------|-------------------------------|---------------------------------------|------------------------------------|--|-------------------------------|---------------------------------------|

13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN

| | | | |
|--|--------------------------------|------------------------------|--|
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
|--|--------------------------------|------------------------------|--|

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

| | | | |
|---|-------------------------------|--|---|
| <input type="checkbox"/> Barn | <input type="checkbox"/> Shed | <input checked="" type="checkbox"/> Garage | <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden | corn crib |
| | | | mature trees |

15. SURROUNDING ENVIRONMENT

| | | | |
|---|---|---|---|
| <input checked="" type="checkbox"/> Open land | <input checked="" type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Industrial | <input type="checkbox"/> Rural | <input type="checkbox"/> High building density |

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
 Sited on level plot west side of North St. facing east. North St contains a large number of antique houses and is part of potential Historic District

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

Central chimney, 3 fireplaces-one in each room with original mantels (1 closed).
 Paneled doors, original latches.
 Early kitchen addition has fireplace (closed).
 Second addition built c. 1860 contains another room.
 Windows-1st floor 6/6, second floor 3/3.
 Small porch on left to front door has turned posts.
 House is relatively unaltered, though it is probable that it was originally clapboarded rather than shingled.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Built by Seth Russell, (1824-1900) great grandson of the Rev. Samuel Russell. Seth Russell married 3 times and after 3rd. marriage in 1858 sold house to Hiram Holabird. His grandson, Douglas Holabird, resides there now.
 Douglas Holabird was Selectman 1920-1924 & 1938-1951,

SOURCES

Assessor's Record 26-18
 County Map 1856
 Beers Atlas 1868
 Martha Russell's Notes
 Talk with owner.

PHOTO
COMPILED BY

PHOTOGRAPHER

Ruth Arnold

5/79

VIEW

Front

NEGATIVE ON FILE

yes

NAME


Janet Gegan

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known Highways Vandalism Developers Other _____
- Renewal Private Deterioration Zoning Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 172

IDENTIFICATION

1. BUILDING NAME (Common) *Holabird House* (Historic) *Charles F. Holabird*

2. TOWN CITY *North Branford* VILLAGE *North Branford* COUNTY *New Haven*

3. STREET AND NUMBER (and or location) *52 North St.*

4. OWNER(S) *Miss May B. Holabird* Public Private

5. USE (Present) *Residence* (Historic) *Residence*

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN

DESCRIPTION

7. STYLE OF BUILDING *Victorian Country House* DATE OF CONSTRUCTION *1879*

8. MATERIAL(S) (Indicate use or location when appropriate)

Clapboard Asbestos Siding Brick Other (Specify) _____

Wood Shingle Asphalt Siding Fieldstone

Board & Batten Stucco Cobblestone

Aluminum Siding Concrete Type: _____ Cut stone Type: *Sandstone foundation*

9. STRUCTURAL SYSTEM

Wood frame Post and beam balloon

Load bearing masonry Structural iron or steel

Other (Specify) _____

10. ROOF (Type)

Gable *4 Gables Bay* Flat Mansard Monitor sawtooth

Gambrel Shed Hip Round Other (Specify) _____

(Material)

Wood Shingle Roll Asphalt Tin Slate

Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES *2 + full att* APPROXIMATE DIMENSIONS *35' x 35'*

12. CONDITION (Structural) Excellent Good Fair Deteriorated (Exterior) Excellent Good Fair Deteriorated

13. INTEGRITY (Location) On original site Moved WHEN? (Alterations) Yes No IF YES, EXPLAIN

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

Barn Shed Garage Other landscape features or buildings (Specify)

Carriage house Shop Garden *Extensive gardens*

15. SURROUNDING ENVIRONMENT

Open land Wood-land Residential Scattered buildings visible from site

Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS

House is located in large piece of land on west side of North St. in an area of several antique homes. To south is the Timothy Russell house. Across st. is the Rev. Samuel Eell's house. To North is the Seth (600 ft.) Russell house. Riv runs through rear portion.

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

1. Authentic interior
2. Two story bay window off dining room.
3. One interior wall removed and bathrooms added.
4. 2/2 windows throughout with substantial, bracketted sills. Gable windows curved slightly at top.
5. Light, simple gable decoration composed of a king post and tie beam with two 2/3 circular arcs back to back in the resulting triangles.

18 ARCHITECT

BUILDER

By/for Charles F. Holabird

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

In the rear of house there was an old foundation once occupied by a family named Stedman who kept a tavern there. May Holabird, daughter of Charles Holabird, and now owner, has found old English coins in area of old foundation. Miss Holabird is a descendant of the Rev. Samuel Russell and daughter of Charles F. Holabird.

SOURCES

Martha Russell - Notes relating to Early Settlers of North Branford. Talk with owner, Miss May Holabird.

PHOTOGRAPHER

Ruth Arnold 6/79

VIEW

Side(south)

NEGATIVE ON FILE

yes



COMPILED BY

NAME Janet Gegan 6/1/79

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472

20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanaton _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 173

IDENTIFICATION

1. BUILDING NAME (Common) Samuel Fells House (Historic) Samuel Fells House

2. TOWN CITY North Branford VILLAGE North Branford COUNTY New Haven

3. STREET AND NUMBER (and or location) 45 North St.

4. OWNER(S) Perry Stebbins Odell Public Private

5. USE (Present) Residence (Historic) Residence

6. ACCESSIBILITY TO PUBLIC: Yes No EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE IF YES, EXPLAIN Yes No

7. STYLE OF BUILDING Colonial DATE OF CONSTRUCTION 1769

DESCRIPTION

8. MATERIAL(S) (Indicate use or location when appropriate)

Clapboard Asbestos Siding Brick Other (Specify) _____

Wood Shingle Asphalt Siding Fieldstone

orig. clapboarded

Board & Batten Stucco Cobblestone

Aluminum Siding Concrete Type: _____ Cut stone Type: Red sandstone chimney and foundation

9. STRUCTURAL SYSTEM

Wood frame Post and beam balloon

Load bearing masonry Structural iron or steel

Other (Specify) _____

10. ROOF (Type)

Gable Flat Mansard Monitor sawtooth

Gambrel Shed Hip Round Other (Specify) _____

(Material)

Wood Shingle Roll Asphalt Tin Slate

Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES 2 + attic APPROXIMATE DIMENSIONS 44' x 48' main house, 17' x 10' rear shed, 10' x 20' so. porch.

12. CONDITION (Structural) (Exterior)

Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN

On original site Moved Yes No

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

Barn Shed Garage Other landscape features or buildings (Specify) Substantial plantings at base of house. Well at rear of house.

Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT

Open land Wood-land Residential Scattered buildings visible from site

Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS

Situated on a small hill on the east side of North St., the building is placed in a surrounding which retains historical character and is part of an architecturally related building cluster which might be a poten-

tial historic district.

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

A large post and beam house with 10 summers. Many posts and girts throughout are boxed with beaded corners. The rear kitchen at the first floor has a fireplace with bake oven, reduced in size by present owner. Door to stairs located in this room is composed of 2 feather edge boards. The Northwest room contains panelling on fireplace wall with an arched bol-lection moulding around fireplace and single board mantel. A corner cupboard is situated in northwest corner with moulded cornice, key at center, vertically grooved pilasters and double leaf doors under. This room has original floors as well as moulded chair rail in plaster walls. Hewn beams are exposed. The southwest room also is panelled on the fireplace wall with new fireplace trim by present owner. Panelled, 2' x 4" high wainscot on west, south and east walls. 3' - 2" wide "funeral door" on south wall at front corner. Evidence on west front wall of original

(Cont.)

18 ARCHITECT

BUILDER

By/for Samuel Eells

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

1. Samuel Eells; son of Rev. Edward Eells of Middletown, Conn. was second pastor of No. Branford Cong. Church. He purchased 10 acres of land from Eunice Rose and built this house when he began his ministry in 1769.
2. Samuel Eells served as Captain of a 60 man company in January, 1777 for 28 days.
3. House was acquired by David & Mary Russell Reynolds Palmer in 1808 and has passed through 4 generations to wife of present owner, Perry Odell.

SOURCES

Assessor's record 26-27
 WPA form - No. 12
 Introduction to Samuel Eells, by Edna G. Hall, delivered Jan. 27, 1972.
 County Maps 1852-1856.
 Beers Atlas Map 1868.
 Martha Russell's - Notes Relating to Early Settlers

PHOTO
 COMPILLED BY

PHOTOGRAPHER

Robert Van Nest

1977

VIEW

Front

NEGATIVE ON FILE

yes

NAME

Janet S. Grogan

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known Highways Vandalism Developers Other _____
- Renewal Private Deterioration Zoning Explanation _____

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford, Connecticut 06106
HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

FOR OFFICE USE ONLY

TOWN NO.:

SITE NO.:

UTM: 18/---/---/---/---/---

QUAD:

DISTRICT: S NR: ACTUAL
POTENTIAL

CONTINUATION SHEET

Item number: 173 Date: _____

Item number 17

stair to second floor room at front of center chimney, probably study. This stair was removed probably around 1810 and conventional center stair installed. This was removed in 1947 by present owner. Front, entry hall has smoke oven with bake oven on chimney wall.

Upstairs, the study contains a small fireplace with panelling on chimney wall, large center panel is 1'-9" x 5'-6". The northwest bedroom fireplace is covered over, posts and girts exposed. The southwest bedroom has a small fireplace, posts and girts are plastered over. The large east room leaves much structure exposed.

The sandstone chimney which services seven fireplaces measures 12'-6" wide x 11'-7" deep in the basement and is pierced by a 5'-5" wide x 5'-0" high arched passage from front to rear. Foundation at front is adapted to accommodate existing bolder. Original, studded, front door is stored in basement.

On exterior, the front entry is composed of six panelled (ea.) double leaf doors. A simple moulded cornice is located above eight round headed transome lights. The nine front windows are wide muntin 12/12 pane. The windows on the north are 6/6 except the single 12/12 gable window. On the east, rear, the windows are varied: 1-narrow 9/9, 1 narrow 4/4, 2 - 12/12. On the south the first floor windows are 12/12, second floor 6/6 with a 12/12 gable window

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES

HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item# 174

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
Gustavus A. Aronson

2. TOWN CITY VILLAGE COUNTY
North Branford North Branford New Haven

3. STREET AND NUMBER (and or location)
43 North Street

4. OWNER(S)
Paul & Bridie A. Tracey Public Private

5. USE (Present) (Historic)
Residence Residence

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
Bungalow 1924

8. MATERIAL(S) (Indicate use or location when appropriate)

| | | | |
|--|--|---|--|
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick Chimney | <input type="checkbox"/> Other (Specify) _____ |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input type="checkbox"/> Fieldstone | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | |
| <input type="checkbox"/> Aluminum Siding | <input checked="" type="checkbox"/> Concrete Type: <u>poured</u> | <input type="checkbox"/> Cut stone Type: _____ | |

9. STRUCTURAL SYSTEM

| | | | |
|--|--|---|---|
| <input checked="" type="checkbox"/> Wood frame | <input type="checkbox"/> Post and beam | <input checked="" type="checkbox"/> balloon | <input type="checkbox"/> Structural iron or steel |
| <input type="checkbox"/> Load bearing masonry | | | |
| <input type="checkbox"/> Other (Specify) _____ | | | |

10. ROOF (Type)

| | | | | |
|---|---------------------------------------|----------------------------------|--|--|
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) _____ |
| (Material) | | | | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) _____ | |

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
1 1/2 + attic 48' x 28'

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN
 On original site Moved Yes No

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify)
 Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
 House sited on slight rise on east side of North St. Driveway to left. Located in a surrounding which retains historical character and is part of an architeturally related building cluster which might be potential

historic district

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

1. Roof slope faces street. Roof breaks to shallower pitch at enclosed porch. Large shed dormer at front.
2. Lattice porch base.
3. Good example of its type, with unaltered exterior.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

1. One of owners, Gastavus Aronsen, was a landscape gardener who cared for houses in vicinity. He created some terrace gardens at rear of house - remnants of terraces can be distinguished.

SOURCES

Assessor records - 26 - 28.
Talk with owners
North Branford Land Records.

PHOTO

PHOTOGRAPHER

Ruth Arnold

5/79

VIEW

front

NEGATIVE ON FILE

yes

COMPILED BY

NAME

Janet S. Grogan

ORGANIZATION

Totoket Historical Society Inc.

ADDRESS

P. O. Box #117, Northford, Conn. 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
- Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

Item # **175**

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No. |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
 Elizur Foote

2. TOWN CITY
 North Branford
 VILLAGE North Branford COUNTY New Haven

3. STREET AND NUMBER (and or location)
 37 North Street

4. OWNER(S)
 Victor L. & Jeanne M. Bortolot Public Private

5. USE (Present) (Historic)
 Residence

6. ACCESSIBILITY TO PUBLIC: Yes No EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN

DESCRIPTION

7. STYLE OF BUILDING
 Greek Revival DATE OF CONSTRUCTION
 c. 1854

8. MATERIAL(S) (Indicate use or location when appropriate)

| | | | |
|---|---|---|--|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input type="checkbox"/> Chimney | <input type="checkbox"/> Fieldstone |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | |
| <input type="checkbox"/> Aluminum Siding | <input checked="" type="checkbox"/> Concrete Type: poured & block | <input type="checkbox"/> Cut stone Type: | |

9. STRUCTURAL SYSTEM

| | | |
|--|---|---|
| <input checked="" type="checkbox"/> Wood frame | <input checked="" type="checkbox"/> Post and beam | <input type="checkbox"/> balloon |
| <input type="checkbox"/> Load bearing masonry | | <input type="checkbox"/> Structural iron or steel |
| <input type="checkbox"/> Other (Specify) | | |

10. ROOF (Type)

| | | | | |
|---|---------------------------------------|----------------------------------|--|--|
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) |
| (Material) | | | | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) | |

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
 2 + attic 55' x 50'

12. CONDITION (Structural) (Exterior)

| | | | | | | | |
|------------------------------------|--|-------------------------------|---------------------------------------|------------------------------------|--|-------------------------------|---------------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
|------------------------------------|--|-------------------------------|---------------------------------------|------------------------------------|--|-------------------------------|---------------------------------------|

13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN

| | | | | |
|---|---|---------|---|--|
| <input type="checkbox"/> On original site | <input checked="" type="checkbox"/> Moved | 4/30/70 | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Interior remodeled several times - latest 1972 |
|---|---|---------|---|--|

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

| | | | |
|---|-------------------------------|---|---|
| <input type="checkbox"/> Barn | <input type="checkbox"/> Shed | <input checked="" type="checkbox"/> Garage attached | <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) Picket fence in front |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden | |

15. SURROUNDING ENVIRONMENT

| | | | |
|---|---|---|---|
| <input checked="" type="checkbox"/> Open land | <input checked="" type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input type="checkbox"/> Rural | <input type="checkbox"/> High building density |

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
 House sited on east side of North St. on level piece of land. Wooded hill rises at rear. This structure is located in a surrounding which retains historical character and is part of an architecturally related building cluster which might be a potential historic district.

(OVER)

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford, Connecticut 06106
HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

CONTINUATION SHEET

Item number: 175 Date: _____

FOR OFFICE USE ONLY

TOWN NO.:

SITE NO.:

UTM: 18 / - / - / - / - / - / - / - / - / - / - / -

QUAD:

DISTRICT:

S

NR:

ACTUAL

POTENTIAL

Item number: 17

7. One original fireplace in rear right room, classical mantel saved.

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| | |
|--|--|
| FOR OFFICE USE ONLY | |
| Town No.: | Site No.: |
| UTM: | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 176

IDENTIFICATION

1. BUILDING NAME (Common) *(Historic)*
 Aubry's Timothy Russell

2. TOWN CITY VILLAGE COUNTY
 North Branford North Branford New Haven

3. STREET AND NUMBER (and or location)
 28 North Street

4. OWNER(S)
 Jules W. Aubry Public Private

5. USE (Present) *(Historic)*
 Residence Residence

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN
 Yes No Yes No

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
 Georgian Colonial - Integral Saltbox c. 1764

8. MATERIAL(S) (indicate use or location when appropriate)
 Clapboard Asbestos Siding Brick Other (Specify) foundation. (dirt floor cellar under north end of house; small cellar under ell.)
 Wood Shingle Asphalt Siding Fieldstone
 Board & Batten Stucco Cobblestone
 Aluminum Siding Concrete Type: Cut stone Type: sandstone chimney

9. STRUCTURAL SYSTEM
 Wood frame Post and beam balloon
 Load bearing masonry Structural iron or steel
 Other (Specify)

10. ROOF (Type)
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify) saltbox
 (Material)
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify)

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
 2 + attic 64' x 48'

12. CONDITION (Structural) *(Exterior)*
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN? *(Alterations)* IF YES, EXPLAIN
 On original site Moved Yes No kitchen ell to west (19" cent. south wing added c. 1970.

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify) attached to barn. stone terraces, brook, two ponds
 Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Industrial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
 House sited west side of North St. on level piece of land that drops off to brook running north-south at rear. Hill rises beyond brook to Great Hill Road.

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

Exterior: 5-bay facade. Original windows (6/6) on second floor; 1st floor windows (6/6) slightly larger replacements. Front door light classical surround; door modern. Southeast corner door closed up 1958.

On terrace back of house is a sandstone sink with long drain. Large sandstone slabs by river carried from Congregational Church after 1910 fire.

Interior: Front stairs: closed string with strongly turned short balusters. Raised paneling below. Upstairs front hall railing support in "Chinese" style. Center chimney intact; 3 fireplaces 1st. floor, one, 2nd in south "chamber". Partitions from south room to original kitchen removed.

(Cont.)

18 ARCHITECT

BUILDER

By/for Timothy Russell

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

1. Timothy Russell, son of Jonathan and Eunice (Barker) Russell married Chloe, daughter of Rev. Jonathan Merrick - Nov. 24, 1764. If this house was built in 1764 it was in a most conservative style as beaded joists and cased summers and posts of this type were out of style some 30 years before.

2. Timothy Russell apparently bought this 1½ acres in 1763. In 1760 he had bought 1½ acres to the north of it.

SOURCES

Assessor's records 26-15
Land Records, North Branford and Branford
County maps 1852 & 1856.
Beers Atlas 1868.
W.P.A. Census #37.
Martha Russell's Notes Relating to Early Settlers.

PHOTO

PHOTOGRAPHER

Robert Van Nest

1977

VIEW

Front

NEGATIVE ON FILE

yes

COMPILED BY


NAME

Totoket Historical Society, Inc.

ORGANIZATION

P. O. Box 117, Northford, CT 06472

ADDRESS



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford, Connecticut 06106
HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

| | | | |
|---------------------|-----------|-----|---------------------|
| FOR OFFICE USE ONLY | | | |
| TOWN NO.: | SITE NO.: | | |
| UTM: 18/ | / | / | / |
| QUAD: | | | |
| DISTRICT: | S | NR: | ACTUAL POTENTIAL |

CONTINUATION SHEET

Item number: 176 Date: _____

Item number 17:

South room: wide-beaded casings on summer and girts; beaded joists. Summer, girts and posts meet at uneven levels as in very early construction. Fireplace surround and mantel "Federal"; possibly added to earlier fireplace.
Simple open round arched corner cupboard (with one panel door below) originally in south west corner; moved to kitchen 1958.
North room: Beaded casings on summer, girts & posts. Bolection molding around fireplace. Sheathing modern.
West room: original kitchen fireplace uncovered behind concrete ell 1958. Sandstone hearthstone was originally a doorstep from a Harrison house destroyed for Lake Gaillard. Vertical feather-edge whitewood sheathing - some original and some replaced.
Second floor: cased summer, girts and posts in south chamber; fireplace (mantel shelf new); vertical feather-edge whitewood sheathing (some re-set).
Back stairway original.

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES

HIST-6 NEW 5 77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION

59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| | |
|--|--|
| FOR OFFICE USE ONLY | |
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 177

| | | |
|--|---|---|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | |
| | Old Congregational Parsonage | Congregational Parsonage |
| | 2 TOWN/CITY | VILLAGE COUNTY |
| | North Branford | North Branford New Haven |
| | 3 STREET AND NUMBER (and/or location) | |
| | 29 North St. | |
| | 4. OWNER(S) | |
| | William B. Coley II <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | |
| | 5 USE (Present) (Historic) | |
| | Residence | Minister's Residence |
| DESCRIPTION | 6 ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN | |
| | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| | 7. STYLE OF BUILDING | |
| | DATE OF CONSTRUCTION | |
| | 1772 | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | |
| | <input checked="" type="checkbox"/> Clapboard underneath | <input type="checkbox"/> Asbestos Siding |
| | <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding |
| | <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco |
| | <input checked="" type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: _____ |
| <input checked="" type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) _____ | |
| | 2 chimneys | |
| | Fieldstone | |
| | Cobblestone | |
| | Cut stone foundation | |
| 9. STRUCTURAL SYSTEM | | |
| <input checked="" type="checkbox"/> Wood frame | <input checked="" type="checkbox"/> Post and beam | |
| <input type="checkbox"/> Load bearing masonry | <input type="checkbox"/> Structural iron or steel | |
| <input type="checkbox"/> Other (Specify) _____ | | |
| 10. ROOF (Type) | | |
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | |
| | <input type="checkbox"/> Mansard | |
| | <input type="checkbox"/> Monitor | |
| | <input type="checkbox"/> sawtooth | |
| | <input type="checkbox"/> Round | |
| | <input type="checkbox"/> Other (Specify) _____ | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Tin | |
| <input type="checkbox"/> Built up | <input type="checkbox"/> Slate | |
| <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) _____ | |
| 11 NUMBER OF STORIES APPROXIMATE DIMENSIONS | | |
| 2 + attic | 60' x 36' | |
| 12 CONDITION (Structural) (Exterior) | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | |
| 13 INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN | | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Interior renovations over the years | |
| 14 RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input checked="" type="checkbox"/> Garage | <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) | |
| | Swimming pool | |
| <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | |
| 15 SURROUNDING ENVIRONMENT | | |
| <input checked="" type="checkbox"/> Open land <input type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Scattered buildings visible from site | |
| <input type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial <input type="checkbox"/> Rural | <input type="checkbox"/> High building density | |
| 16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| House sited on east side of North St. across from intersection of Church St. on a level site with wooded hill rising in rear. Structure is part of an architecturally related building cluster which might be a potential historic district. | | |

(OVER)

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

1. Large fireplace in rear 1½ story ell.
2. Rear ell has 4/4 horizontal stomach windows under roof line.
3. Three cut stone entrance steps; four cut stone steps set in rise of ground lead to main entrance.
4. Four light vertical windows on each side of door with panels below. Flared canopy.
5. Center chimney removed, front door probably altered at same time.
6. 5 bay front, symmetrical, uneven window placement.

18 ARCHITECT _____ BUILDER By/for Daniel Rose

SIGNIFICANCE

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

1. Daniel Rose married Sara Frisbie in 1771. House built sometime between 1768 & 1774.
2. House bought in 1809 by Charles Atwater, third minister of church, for his residence until he died from typhoid fever in 1825. The North Branford town library is named in his memory.
3. Used as parsonage for N. B. Congregational Church from 1838-1952. Subscription started to raise money to buy a parsonage - April 14, 1838. L. R. 1-551 lists subscribers and shares. Purchased from Jasper and Betsey Munro, March 30, 1838.

SOURCES

| | |
|--|-----------------------------------|
| Assessor record 26-3 | Branford Land Records 9-71 & 9-44 |
| W.P.A. Census of Old Buildings #11 | 2nd Society Church Records |
| County Maps 1852-1856 | 1769-1808 |
| Beers Atlas Map 1869 | N. B. Land Records 1-550 |
| History of the N. B. Congregational Church - Edna Hall | |
| Martha Russell's Notes | |


PHOTOGRAPHER Robert Van Nest 1977

VIEW Left front NEGATIVE ON FILE yes

COMPILED BY NAME Janet S. Gregan 1/80

ORGANIZATION Totoket Historical Society, Inc.

ADDRESS P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

None known Highways Vandallism Developers Other _____

Renewal Private Deterloration Zoning Explanation _____

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

Front yard is terraced by using large blocks of cut sandstone as retaining walls - 2 levels. Dates from Civil War period. Four front steps are large slabs of cut sandstone - top step 4'X 8'. Double leaf raised paneled door; applied molding pilasters probably not original. Six light transom over door - each light has rounded-head panes. 3" overhang at top of first and second story, wraps around all four sides. In 1921 interior of house was gutted and remodeled - owner says few original features are left. The rear ell dates from this time. "Coffin door" at southeast corner. Original fireplace remains; 1st floor has 3 fireplaces, 2nd floor has two. Chestnut frame. Originally there was a pond and barn to rear.

SIGNIFICANCE

18 ARCHITECT

BUILDER

Nathan Harrison

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

"Justus Rose contracted with Nathan Harrison to build house for his daughter Abigail and her husband Beverly Munro. Nathan married for the second time and wanted the house. Mr. Rose agreed."(1)
Nathan Harrison bought the land on Dec. 3, 1795 from Asenath Palmer. In 1878 there was a house there when he bought more land from Abigail Palmer and Beverly Munro.(2)
Kate Goodbody (May Holabird's aunt) bought house in 1920 after her husband, William W. Goodbody, died of cancer in Ireland. He was the brother of Robert Goodbody, a partner of Charles Dow. She renovated the house.(3)
William Woodcock Goodbody (1866-1908) "Irish banker, an original director of Marconi Co."(4)

SOURCES

Assessor record 26-31. (3) Talk with May Holabird, 8/1977
WPA Census #18 (4) Portrait Index - Yale, 1951
County Maps 1852 & 1856
Beers Atlas Map - 1868
(1) Martha Russell's Notes
(2) Branford Land Records 12-350; 13-233.

PHOTO

PHOTOGRAPHER

Robert Van Nest

1977

VIEW

Left front- northwest

NEGATIVE ON

yes

COMPILED BY

NAME

Janet S. Grogan

1/1980

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P.O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE
 None known Highways Vandalism Developers Other _____
 Renewal Private Deterioration Zoning Explanaton _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No. |
| UTM: | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 179

| | | |
|--|---|----------------------------------|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | |
| | Smith house-Smith Shop | Jared Chidsey (orig. Hart House) |
| | 2 TOWN CITY | VILLAGE COUNTY |
| | North Branford | North Branford New Haven |
| | 3 STREET AND NUMBER (and or location) | |
| | 11 North St. | |
| | 4 OWNER(S) | |
| | Mrs. Herman Smith (Liela P.) <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | |
| | 5 USE (Present) (Historic) | |
| | 2 family residence & yarn shop residence | |
| DESCRIPTION | 6 ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN | |
| | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No except for small shop in rear | |
| | 7. STYLE OF BUILDING DATE OF CONSTRUCTION | |
| | Colonial/Greek Revival c. 1785-1850 | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | |
| | <input checked="" type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input checked="" type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) _____ 3 chimneys <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input checked="" type="checkbox"/> Fieldstone foundation <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input checked="" type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input checked="" type="checkbox"/> Concrete Type: poured foundation-left addition <input checked="" type="checkbox"/> Cut stone Type: sandstone-front foundation | |
| | 9. STRUCTURAL SYSTEM | |
| | <input checked="" type="checkbox"/> Wood frame <input checked="" type="checkbox"/> Post and beam <input type="checkbox"/> balloon <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____ | |
| | 10 ROOF (Type) | |
| | <input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ (Material) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ | |
| 11 NUMBER OF STORIES APPROXIMATE DIMENSIONS | | |
| 2 + attic 72' x 42' | | |
| 12 CONDITION (Structural) (Exterior) | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| 13 INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN | | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Additions & remodeling | | |
| 14 RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input checked="" type="checkbox"/> Garage <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) Picket fence, large trees <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | |
| 15 SURROUNDING ENVIRONMENT | | |
| <input checked="" type="checkbox"/> Open land <input checked="" type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial <input type="checkbox"/> Rural <input type="checkbox"/> High building density | | |
| 16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| Sited on east side of North St., facing west on large lawn area that ends in a steep wooded hill at rear. Library Place and Atwater Library are just to south. Structure is part of an architecturally related building cluster which might be a potential historic district. | | |

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

1. 5 bay, front windows 1/1. In south gable, 4 light horizontal pediment window-in north gable, 6/6 double hung window, in rear gable in 2 story ell are 2 small windows, one original 6 light, the other 1 light replacement.
2. Portico with square posts with applied collaring and plinths. 3 light side windows at door-panel underneath repeats detail on portico posts.
3. Interior completely altered-very little original remains.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Possibly original house was built for Nathan Palmer's four daughters, Asenath, Abigail, Huldah & Rebecca in 1785 when they sold original homestead which stood just south of present house to Philemon Harrison in 1786. Rebecca was only one that married-a Dennis Hart- and according to one deed (B. 17-28) it was referred to as the Hart House. It eventually came into the hands of Jared Chidsey who married for the first time, Harriet Wheaton, daughter of Deacon Daniel Wheaton, on Nov. 3, 1828. Jared Chidsey lived there until he died in 1869 and it went to his fourth wife Julia. Jared also acquired the older house to the south in 1868 and tore it down. Nathan Palmer who built older house c. 1764 had acquired 17 acres from Timothy Barker in 1763. He deeded one portion, approximately 10 rds. square, to the town for use as a "Place of Parade & Pubick Exercise". The Atwater Memorial Library was built on this piece. Jared Chidsey was a farmer & a shoemaker according to death notice. He must have been prosperous, bought & sold several pieces of land (Cont

SOURCES

Branford & North Branford Land Records
 County Maps 1852-1856
 Beers Atlas 1868
 Talk with owner, Mrs. Smith
 Talk with Douglas Holabird
 Martha Russells Notes

PHOTOGRAPHER

Ruth Arnold

6/79

VIEW

NEGATIVE ON FILE

Front

yes

NAME

Janet S. Gegan


4/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known Highways Vandalism Developers Other _____
- Renewal Private Deterloration Zoning Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| | |
|--|--|
| FOR OFFICE USE ONLY | |
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 180

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
 Zion Episcopal Church | Zion Episcopal Church

2. TOWN/CITY | VILLAGE | COUNTY
 North Branford | North Branford | New Haven

3. STREET AND NUMBER (and or location)
 Notch Hill Road

4. OWNER(S)
 Zion Episcopal Church Public Private

5. USE (Present) (Historic)
 Place of Worship | Place of Worship

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD | INTERIOR ACCESSIBLE | IF YES, EXPLAIN
 Yes No | Yes No | Nursery School - Public Worship - Meetings

DESCRIPTION

7. STYLE OF BUILDING | DATE OF CONSTRUCTION
 Transitional (Federal - Gothic Revival) | 1818-1840

8. MATERIAL(S) (Indicate use or location when appropriate)
 Clepboard Asbestos Siding Brick Other (Specify) _____
 Wood Shingle Asphalt Siding Fieldstone
 Board & Batten Stucco Cobblestone
 Aluminum Siding Concrete Type: Poured Foundation Cut stone Type: _____

9. STRUCTURAL SYSTEM
 Wood frame Post and beam balloon
 Load bearing masonry Structural iron or steel Parish hall
 Other (Specify) _____

10. ROOF (Type) | (Material)
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify) Dome on belfry
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES | APPROXIMATE DIMENSIONS
 1 1/2 | 52' x 40' church 46' x 66' Belfry 48' high Connected parish hall

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated | Excellent Good Fair Deteriorated

13. INTEGRITY (Location) | WHEN? | (Alterations) | IF YES, EXPLAIN
 On original site Moved 1957 | Yes No | Parish hall added

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify) Parking area Children's play area
 Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
 Building sited on west side of road, faces east. Parish house addition is to south. There is a curved drive in front and parking area on south. There are residences further south and across road area to rear & (OVER)
 north is wooded.

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

1. Relatively unaltered.
2. Square tower projects from front of building with a pointed arched octagonal belfry and dome from the top of which arises a turned wooden finial which supports a gold cross.
3. Original gothic window frames with intersecting tracery motifs. Front windows retain original triple hung sash. Sidewall windows contain stained glass in geometric patterns installed in 1866. One window is a biblical scene given in memory of Father Smith, 1957.
4. Interior is original-gallery supported by columns. Extends completely across rear and partially along sides.

18 ARCHITECT

BUILDER

Capt. Abraham Coan

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE


1. Captain Coan also built North Guilford Congregational Church. Captain Coan did not work with architect but was probably familiar with work of David Hoadley. The Belfry can be seen in several of Hoadley's churches.
2. This is the oldest original church and public building in No. B.
3. Church was consecrated May 13, 1864.
4. Cornerstone found when building was moved reads "Zion Church - Founded May 19, 1819".
5. Church was moved from original site on Foxon Road in 1957 because there was need for expansion.

SOURCES

Jane Hooker - Church historian and author of Zion Church History, "Story of a Country Parish" 1977.

COMPILED BY PHOTO

| | | | |
|--------------|------------------------------------|------------------|---------|
| PHOTOGRAPHER | Ruth Arnold | DATE | 5/79 |
| VIEW | Front | NEGATIVE ON FILE | yes |
| NAME | Janet S. Gegan | DATE | 1/16/80 |
| ORGANIZATION | Totoket Historical Society, Inc. | | |
| ADDRESS | P. O. Box 117, Northford, CT 06472 | | |



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

| | | | | |
|--|-----------------------------------|--|-------------------------------------|---|
| <input checked="" type="checkbox"/> None known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input checked="" type="checkbox"/> Other |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Zoning | <input type="checkbox"/> Ex |

FOR OFFICE USE ONLY

Town No.: _____ Site No.: _____

UTM: _____

QUAD: _____

DISTRICT: S NR IF NR SPECIFY Actual Potential

Item # 181

| | | |
|---|---|--------------------------|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | |
| | Linsley Lake Cottages | |
| | 2. TOWN CITY | VILLAGE COUNTY |
| | North Branford | North Branford New Haven |
| | 3. STREET AND NUMBER (and or location) | |
| | Twin Lakes Rd. - off | |
| | 4. OWNER(S) #33 Dr. Theodore Evans, #29 C. Forbes Sargent, #25 Marshall Williams Family, #19 Jane Day Hooker(Cont.) <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | |
| | 5. USE (Present) (Historic) | |
| | Residences & Summer Cottages Fishing Camps & Summer Cottages | |
| | 6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
| 7. STYLE OF BUILDING | | |
| Simple Bungalow Cabin | | |
| DATE OF CONSTRUCTION | | |
| c. 1900 and 1935 | | |
| 8. MATERIAL(S) (Indicate use or location when appropriate) | | |
| <input checked="" type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input checked="" type="checkbox"/> Brick <input checked="" type="checkbox"/> Other (Specify) log chimneys | | |
| <input checked="" type="checkbox"/> Wood Shingle <input checked="" type="checkbox"/> Asphalt Siding <input type="checkbox"/> Fieldstone | | |
| <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone | | |
| <input type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: block, poured <input checked="" type="checkbox"/> Cut stone Type: Granite chimneys | | |
| 9. STRUCTURAL SYSTEM | | |
| <input checked="" type="checkbox"/> Wood frame <input checked="" type="checkbox"/> Post and beam <input checked="" type="checkbox"/> balloon | | |
| <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel | | |
| <input checked="" type="checkbox"/> Other (Specify) log | | |
| 10. ROOF (Type) | | |
| <input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth | | |
| <input type="checkbox"/> Gambrel <input checked="" type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) | | |
| (Material) | | |
| <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate | | |
| <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) | | |
| 11. NUMBER OF STORIES | | |
| 1-stepped | | |
| APPROXIMATE DIMENSIONS | | |
| Some now levels in some Original cottages in range of 20' x 25', expanded 30'x50'+ | | |
| 12. CONDITION (Structural) (Exterior) | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | |
| 13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN | | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Most of these cottages have received additions & alterations (Cont.) | |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input checked="" type="checkbox"/> Garage <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) | | |
| <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | Small docks on Linsley Lake. | |
| 15. SURROUNDING ENVIRONMENT | | |
| <input checked="" type="checkbox"/> Open land <input checked="" type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input checked="" type="checkbox"/> Scattered buildings visible from site | | |
| <input type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial <input type="checkbox"/> Rural <input type="checkbox"/> High building density | | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| All seven cottages are located on the east shore of Linsley Lake and west side of Twin Lakes Rd.-Off, and are sited at the top of an embankment. Secluded Twin Lakes Rd.-off is heavily treed on the lake side and opens to a meadow on the east side. It finishes in a dead end. | | |

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

Taken individually these buildings are not of outstanding architectural importance, but as a group they are quite unique. The cottages, dating from c. 1900 and c. 1935, have been well maintained by original and subsequent owners. Additions, many and varied, include such modern elements as glass floor to ceiling window walls. The net result is of a tight, little summer community well placed in the landscape with a sophistication brought on by many tasteful additions over the years.

18 ARCHITECT none originally, though at least one, William DeCossy #3, latter additions.

BUILDER Guy Barker and others

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Linsley and Cedar Lake properties began to be assembled in the early 1900's by the Branford Water Co., because of their importance as feeder to the Branford Supply Ponds. In 1923, this company merged with New Haven Water Co. and purchasing of these lake properties continued. At this time the planning and subsequent construction of the Lake Gaillard Reservoir took place, it being completed in 1928 and coming into full use in 1932. The Branford Supply Ponds and the feeder lake properties were then phased out and slowly sold off. Three fishing camps were built on the lake c. 1900-1910, #33, #25 and one on Twin Lakes Rd. subsequently destroyed in the 1938 hurricane. (1) #33 and #25 were never bought by the Water Co. Parcel #19 was sold to Guy Barker on Jan. 5, 1935 by the Water Company on which he built a cottage. Parcels #9 & #7 were sold to New Haven lawyers, Osborn Day and J. Dwight Dana respectively, on Dec. 11, 1935, on which they had cottages built. Parcel #29 was then sold to C. Forbes Sargent (Cont.)

SOURCES

(1) Mrs. Bohne (formerly Mrs. Guy Barker)

PHOTO

PHOTOGRAPHER
Ruth Arnold

VIEW _____ NEGATIVE ON FILE _____

COMPILED BY

NAME
Frank Pannenberg 3/17/80

ORGANIZATION
Totoket Historical Society, Inc.

ADDRESS
P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known Highways Vandalism Developers Other _____
- Renewal Private Deterioration Zoning Explanation _____

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford, Connecticut 06106
HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

| | | | |
|---------------------|-----------|-----|---------------------|
| FOR OFFICE USE ONLY | | | |
| TOWN NO.: | SITE NO.: | | |
| UTM: 18/ | / | / | / |
| QUAD: | | | |
| DISTRICT: | S | NR: | ACTUAL POTENTIAL |

CONTINUATION SHEET

Item number: 188 Date: _____

(Owners Cont.) Item number 4;
#9 Thomas Hooker, #7 Cathryn Hollinger, #3 Charles & Hattie Kulenski

Item number 13;


over the years. The Evans cottage #33 receiving least.

Item number 19;

on Oct. 12, 1936, on which he had a log type cottage built. Parcel #3 was sold to Guy Barker on March 20, 1939, onto which he relocated an old, late 1800's, blacksmith shop from the Maliable Iron Works in Branford. This he converted into a summer cottage. The cottages have since received many additions though the original #33 remains much as when originally built.

In 1945, some residents of this cottage group and others bought the Linsley Farm across the Lake, formed the Linsley Lake Corporation and sold building lots with strict design review controls. This corporation was dissolved in 1973.

OLD FLY 5 COTTAGE
1938 HUNTING
DESTROYED



LINSEY LAKE

FROM WATER CO.

TWIN LAKES RD.

LINSEY LAKE CORP.

ALL THIS LAND ORIGINALLY OWNED BY GEORGE FOSTE PRIOR TO WATER CO.



COMPILED FROM MAP
AT ASSESSORS OFFICE -
OTHER INFORMATION FROM
OTTO SCHAPFER, FORESTER
N.H. WATER CO. AND
CONVERSATIONS WITH
PRESENT OWNERS AND OTHERS

F.P. 3/17/80

ONE OF ORIG. 12
COTTAGES ON LAKE c. 1900

NOW OWNED BY
DR. TED EVANS -
NEVER OWNED BY
WATER CO.

PROPERTY
TO LYN BARRIE
1939

J. DAVID DAVIS
1935

MADE OLD
BUNKER
SITE FROM
DRIVEWAY TO
AND RECONSTRUCTED. LINDY SPARK
CHARLES & JIMMY KUBENSKI (PROPERTY)

SESTRUDE K. DAVIS
1935

THOMAS & JUNE OAK HOLLOW

ADDED - 1939
BY JANE OAK
HOOKER

1939. HENDERSON
OWNERS 1939-1940

1939. HENDERSON
OWNERS 1939-1940

1939. HENDERSON
OWNERS 1939-1940

ELIZ SARGENT
1936-37

LAST ADDITION 1940

1939. HENDERSON
OWNERS 1939-1940

#33

#25

#19

#29

#27

#23

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item# 182

| | | | | |
|----------------|--|----------------------|---------------------|--|
| IDENTIFICATION | 1. BUILDING NAME (Common) <i>(Historic)</i> The Livingston House | | Capt. Joseph Foote | |
| | 2 TOWN CITY North Branford | VILLAGE Northford | COUNTY New Haven | |
| | 3 STREET AND NUMBER (and or location) 5 Old Forest Road | | | |
| | 4. OWNER(S) The Misses Helen H. & Elizabeth A. Livingston <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | | | |
| | 5 USE (Present) <i>(Historic)</i> Residence | | Farm | |

| | | | | | |
|-------------|--|--|---|---|---------------------------------|
| DESCRIPTION | 6 ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | EXTERIOR VISIBLE FROM PUBLIC ROAD <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | INTERIOR ACCESSIBLE <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | IF YES, EXPLAIN |
| | 7. STYLE OF BUILDING Colonial (originally Salt Box construction) | | | | DATE OF CONSTRUCTION c. 1708 |

| | | | | | |
|--|---|---|--|------------|--|
| 8. MATERIAL(S) (Indicate use or location when appropriate) | | | | | |
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick Chimney | <input type="checkbox"/> Other (Specify) | Foundation | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input checked="" type="checkbox"/> Fieldstone | | | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | | | |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: _____ | <input type="checkbox"/> Cut stone Type: _____ | | | |

| | | | | | | |
|---|--|---|--|---|-------------------------------------|--|
| DESCRIPTION | 9 STRUCTURAL SYSTEM | | | | | |
| | <input checked="" type="checkbox"/> Wood frame | <input checked="" type="checkbox"/> Post and beam | <input type="checkbox"/> balloon | | | |
| | <input type="checkbox"/> Load bearing masonry | <input type="checkbox"/> Structural iron or steel | | | | |
| 10 ROOF (Type) | | | | | | |
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth | | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round | <input checked="" type="checkbox"/> Other (Specify) | part of orig. salt box still shows. | |
| (Material) | | | | | | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | | | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) | | | |

| | | | | | |
|---|--|--|---------------------------------------|------------------------------------|--|
| 11 NUMBER OF STORIES 2 + attic | | APPROXIMATE DIMENSIONS 37' across front, 32' deep on North end, 26' on South end. | | | |
| 12 CONDITION (Structural) <i>(Exterior)</i> | | | | | |
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated |

| | | | | |
|--|--------------------------------|--------|---|-----------------|
| 13 INTEGRITY (Location) | | WHEN ? | (Alterations) | IF YES, EXPLAIN |
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | See over |

| | | | | | |
|---|--|--|--|--------------------------------------|--|
| 14 RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | | | | |
| <input checked="" type="checkbox"/> Barn | <input checked="" type="checkbox"/> COW shed | <input checked="" type="checkbox"/> hay | <input checked="" type="checkbox"/> Original wagon house | Milk cooling house, Now a tool shed. | |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input checked="" type="checkbox"/> Garden | Other landscape features or buildings (Specify) | | |

| | | | | | |
|---|--------------------------------------|---|---|--|--|
| 15 SURROUNDING ENVIRONMENT | | | | | |
| <input checked="" type="checkbox"/> Open land | <input type="checkbox"/> Wood-land | <input type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site | | |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input checked="" type="checkbox"/> Rural | <input type="checkbox"/> High building density | | |

| | | | | | |
|--|--|--|--|--|--|
| 16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | | | | |
| House built very close to original North Branford-Northford Road. Faces S.W. overlooking 1707 Foote mill site and Farm River, Hay Field separates house from Rt. 22 on East. Present garage barn formerly wagon shed & horse house (cont.) | | | | | |

(OVER)

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

- 1) Originally a four-room saltbox. Chimney (part clay-laid unfired brick and fieldstone) changed when house converted to two full stories.
- 2) Downstairs back fireplace added to chimney as new kitchen when salt-box leanto was extended;
- 3) 2nd. floor smoke oven (orig. wood door).
- 4) Some windows originally casement.
- 5) Fanlight (with lead decoration) over front door c. 1790. Windows (except attic and 3 downstairs) unbalanced 8/12 (6" x 8" lights); 5 bay front.
(Cont.)

18 ARCHITECT

Unknown

BUILDER

Built for Capt. Joseph Foote

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

One of oldest houses in town. Shows transition from orig. to present building. Hay barn built c. 1900 on older foundation but braced frame, mortise and tenon pegged framing. Saw mill across road disintegrated completely by 1930's.

SIGNIFICANCE

SOURCES

Owners' architectural investigations; land & probate records in N. Bfd., Bfd., Guilford & Wallingford genealogies.
J. F. Kelly interview with previous owner in 1940's.
Branford Land V p. 149 - Dec. 25, 1729 "together with buildings thereon."
Saw mill across road 1707-
Branford Land Records IX p. 257 Nov. 15, 1771 (cont.)

PHOTO

PHOTOGRAPHER

Robert Van Nest 1977

VIEW

Front

NEGATIVE ON I

Yes

COMPILED BY

NAME


Helen H. Livingston 1/1/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterloration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No. |
| UTM: | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 183

| | | | | |
|---|---|---|---|---|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | | Waltonian Club | |
| | 2. TOWN CITY | VILLAGE | COUNTY | |
| | North Branford | Northford | New Haven | |
| | 3. STREET AND NUMBER (and or location) | | | |
| | 2 Old Forest Rd., W. side of Old Forest Rd., east of Farm River | | | |
| | 4. OWNER(S) | | <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | |
| | Mr. & Mrs. E. Scott-Eddy | | | |
| | 5. USE (Present) | | (Historic) | |
| | Residence | | Fishing club, originally residence | |
| | 6. ACCESSIBILITY TO PUBLIC: | | EXTERIOR VISIBLE FROM PUBLIC ROAD | INTERIOR ACCESSIBLE |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | |
| 7. STYLE OF BUILDING | | | DATE OF CONSTRUCTION | |
| Greek Revival | | | c. 1835 | |
| 8. MATERIAL(S) (Indicate use or location when appropriate) | | | | |
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick chimney | <input type="checkbox"/> Other (Specify) _____ | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input checked="" type="checkbox"/> Fieldstone foundation | | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | | |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: _____ | <input type="checkbox"/> Cut stone Type: _____ | | |
| 9. STRUCTURAL SYSTEM | | | | |
| <input checked="" type="checkbox"/> Wood frame | <input checked="" type="checkbox"/> Post and beam | <input type="checkbox"/> balloon | | |
| <input type="checkbox"/> Load bearing masonry | <input type="checkbox"/> Structural iron or steel | | | |
| <input checked="" type="checkbox"/> Other (Specify) | House has been rebuilt (see #17) | | | |
| 10. ROOF (Type) | | | | |
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) _____ |
| (Material) | | | | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) _____ | |
| 11. NUMBER OF STORIES | | APPROXIMATE DIMENSIONS | | |
| 2 + attic | | South wing 10' x 19' depth. House 22' front x 30' deep + 8' porch to west. | | |
| 12. CONDITION (Structural) (Exterior) | | | | |
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated |
| 13. INTEGRITY (Location) | | WHEN ? | (Alterations) | IF YES, EXPLAIN |
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | wing added |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | | | |
| <input checked="" type="checkbox"/> Barn | <input type="checkbox"/> Shed | <input type="checkbox"/> Garage | <input type="checkbox"/> Other landscape features or buildings (Specify) | |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden | | |
| 15. SURROUNDING ENVIRONMENT | | | | |
| <input checked="" type="checkbox"/> Open land | <input type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site | |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input checked="" type="checkbox"/> Rural | <input type="checkbox"/> High building density | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | | | |
| House near south junction of Old Forest Rd. & Forest Rd. (Rt. 22). Situated on steep slope above Farm River. Overlooks hayfield belonging to Donald Augur. Seasonal brook in ravine to south. | | | | |

(OVER)

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

1. House remodeled by Frederik S. Eaton 1941. Roof raised to make more useable second floor and attic. Fireplace in livingroom rebuilt and also cellar fireplace.
2. Typical small Greek Revival style house. Nicely situated. Gable end to road. Rectangular gable window on west side.
3. Original paneled front door with 4 pane side-lights. Broad pilasters and deep entablature over door.
4. Windows 6/6 have pediment shaped heads.
5. Original staircase.
6. Barn had horse stalls on first floor, loft overhead, wagon shed (now 2 car garage) underneath.

18 ARCHITECT

BUILDER

SIGNIFICANCE

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

1. Probably built by/for Samuel Bartholomew prior to 1843.
2. Remodeled in 1896 for use by a fishing club, the Waltonian Club, a group from New Haven; used 1896-1941.

SOURCES

Land Records - North Branford - Vol. 2
 Beers Map 1868
 County Map 1852 & 1856

PHOTO

PHOTOGRAPHER

Ruth Arnold 6/79

VIEW

Left front

NEGATIVE ON FILE

yes

COMPILED BY

NAME

Helen H. Livingston 2/11/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- | | | | | |
|--|--|--|-------------------------------------|--------------------------------------|
| <input checked="" type="checkbox"/> None known | <input checked="" type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Other |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Zoning | <input type="checkbox"/> Explanation |
- Town/State highway to very near house

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

Item # **184**

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM: | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

| | | |
|---|---|---------------------|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | |
| | Simpson House | Josiah Pitt Linsley |
| | 2. TOWN CITY | VILLAGE COUNTY |
| | North Branford | Northford New Haven |
| | 3. STREET AND NUMBER (and or location) | |
| 300 Old Post Road | | |
| 4. OWNER(S) | | |
| James and Randolph Simpson <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | | |
| 5. USE (Present) (Historic) | | |
| Residence and antique shop in barn Farm house | | |
| 6. ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | |
| EXTERIOR VISIBLE FROM PUBLIC ROAD: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | |
| INTERIOR ACCESSIBLE: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | |
| IF YES, EXPLAIN | | |

| | | | | |
|--|--|--|--|---|
| DESCRIPTION | 7. STYLE OF BUILDING | | DATE OF CONSTRUCTION | |
| | Colonial and Victorian | | 1790; east wing in 1880 | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | | | |
| | <input checked="" type="checkbox"/> Original | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) _____ |
| | <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input checked="" type="checkbox"/> Chimneys | <input checked="" type="checkbox"/> Fieldstone Cellar walls |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | | |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: _____ | <input checked="" type="checkbox"/> Cut stone Type: Sandstone foundation* across property wall | | |
| 9. STRUCTURAL SYSTEM | | | | |
| <input checked="" type="checkbox"/> Wood frame | <input checked="" type="checkbox"/> Post and beam | <input checked="" type="checkbox"/> balloon | | |
| <input type="checkbox"/> Load bearing masonry | | <input type="checkbox"/> Structural iron or steel | | |
| <input type="checkbox"/> Other (Specify) _____ | | | | |

| | | | | | |
|---|---|---------------------------------------|--|----------------------------------|--|
| DESCRIPTION | 10. ROOF (Type) | | | | |
| | <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth |
| | <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) _____ |
| | (Material) | | | | |
| | <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) _____ | | |

| | |
|-----------------------|---|
| 11. NUMBER OF STORIES | APPROXIMATE DIMENSIONS |
| 2-1/2 | Main house: 40' X 30'; West wing: 20' X 37'; East Wing: 35' X 27' |

| | | | | | |
|------------------------------------|--|-------------------------------|---------------------------------------|------------------------------------|--|
| 12. CONDITION (Structural) | | (Exterior) | | | |
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good |
| | | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |

| | | | | |
|--|--------------------------------|--------|---|--|
| 13. INTEGRITY (Location) | | WHEN ? | (Alterations) | IF YES, EXPLAIN |
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | 2 wings added. Interior central chimney removed. |

| | | | | |
|--|-------------------------------|--|--|--|
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | | | |
| <input checked="" type="checkbox"/> Barn | <input type="checkbox"/> Shed | <input checked="" type="checkbox"/> Garage | <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) 1) Terraced front lawn with row of maples. | |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input checked="" type="checkbox"/> Garden Perennial | 2) Glass blowing studio at rear l. | |

| | | | | |
|---|-------------------------------------|---|---|--|
| 15. SURROUNDING ENVIRONMENT | | | | |
| <input checked="" type="checkbox"/> Open land | <input type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site | |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Industrial | <input checked="" type="checkbox"/> Rural | <input type="checkbox"/> High building density | |

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS

Located on north side of Old Post Rd. at its intersection with Middletown Ave. Situated on raised, terraced ground with land rising sharply at rear, to the acreage (14 acres). Extensive farm land opposite house across Middletown Avenue through with Farm River flows.

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

The house is comprised of brown stained shingles with white trim. Three brick chimneys, one in center, one on each end. 5 window front with entrance on left-original house. 5 window front with door at center - west wing. Bay window, 1st and 2nd stories on east wing. 12/12 windows on main house 6/6 windows on west wing, with more varied and ornamental windows on east wing. Large, open front porch ties main house with east wing. A substantial sandstone retaining wall is located along the front of the property between the house and road; it is partially cutstone and partially rough. Well house and barn-garage-antique shop with 2nd floor apartment are situated at the west side of the property.

18 ARCHITECT

BUILDER

Josiah J. Linsly 1790

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

About 1790, Josiah Linsly (the 5th generation of Linslys in Conn.) built a new house on land inherited from his father, Lt. Joseph Linsly, who lived at Sol's Path. The house was expanded to the West, early. Same sandstone foundation. The victorian wing on East added in 1880. Evidence of original clapboard siding in interior stair halls and between attic and west wing. Front porch added c.1900.

The unique combination of additions and the synthesis of these elements into a whole is a significant aspect of this house. The original colonial "boxes" have been jointed with a large, Queen Anne - Shingle Style element and interlocked with an extensive front porch. Complete shingling of all elements has further united the building. The effect is that of a large rambling, shingle style house where the individual structures are at once separate and identifiable yet unified. House is still in same family, as original owner. Tollgate on Middletown Tnpk. (charted Oct. 1813) was about one mile northeast.

SOURCES

Beers Atlas 1868.
W.P.A. Census #38.
County Maps 1856.
Family stories.

PHOTO

PHOTOGRAPHER

Ruth Arnold

5/1979

DA

VIEW

Front

NEGATIVE ON FILE

Yes

COMPILED BY

NAME

Lydia L. Davis

5/1979


DA

ORGANIZATION

Totohet Historical Society, Inc.

ADDRESS

P.O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known Highways Vandalism Developers Other _____
- Renewal Private Deterioration Zoning Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES

HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Water # 185

| | | |
|----------------|---|---|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) Schafer Residence Linsley - Alling | |
| | 2. TOWN CITY North Branford | VILLAGE Northford |
| | 3. STREET AND NUMBER (and or location) 276 Old Post Road (Near Northern End) | |
| | 4. OWNER(S) Mr. & Mrs. Robbins P. Schafer <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | |
| | 5. USE (Present) (Historic) Residence Residence | |
| | 6. ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | EXTERIOR VISIBLE FROM PUBLIC ROAD <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| | 7. STYLE OF BUILDING Georgian Colonial - Federal | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | |
| | 9. STRUCTURAL SYSTEM | |
| | 10. ROOF (Type) | |
| DESCRIPTION | 11. NUMBER OF STORIES 2 + attic | |
| | 12. CONDITION (Structural) (Exterior) | |
| | 13. INTEGRITY (Location) | |
| | 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | |
| | 15. SURROUNDING ENVIRONMENT | |
| | 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | |

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

- 1) Central brick chimney. Three fireplaces downstairs, one large with baking oven at right.
- 2) 2 carved mantels. Wainscot in old kitchen. No paneling. Interior det. Federal. Doors have flush paneling on one side, sunk panel reverse.
- 3) Random width floors throughout, some old, some new.
- 4) 9 window front with 6/6 sash.
- 5) Double leaf front door, pilastered frame. New porch over orig. door trim.
- 6) Corner posts show on interior - cased.
- 7) Two small 6/6 sash windows in each gable end.
- 8) Molded cornice, plain board frieze.

18 ARCHITECT -

BUILDER Josiah Linsly

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

- 1) Built by Josiah Linsly for his son Eliakin.
- 2) A federal building carrying over simple Georgian themes.

SOURCES

Deers Atlas 1868
 County Map 1856
 County Map 1852
 Mrs. Eunice Hall Linsly Simpson
 W. P. A. Census of old buildings in Connecticut

PHOTO


PHOTOGRAPHER Ruth Arnold DATE 4/79

VIEW Front NEGATIVE ON FILE yes

COMPILED BY NAME Lydia L. Davis DATE 1/29/80

ORGANIZATION Totoket Historical Society, Inc.

ADDRESS P.O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

None known Highways Vandalism Developers Other _____

Renewal Private Deterioration Zoning Explanaton _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| | |
|--|--|
| FOR OFFICE USE ONLY | |
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # **186**

IDENTIFICATION

| | | | |
|--|---|---|-------------------------|
| 1. BUILDING NAME (Common) Frederick A. Davis House | | (Historic) Thaddeus Maltby | |
| 2. TOWN CITY North Branford | | VILLAGE Northford | COUNTY New Haven |
| 3. STREET AND NUMBER (and/or location) 254 Old Post Road, Northford | | | |
| 4. OWNER(S) Mrs. Frederick A. Davis <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | | | |
| 5. USE (Present) Residence | | (Historic) Residence for 60 acre farm | |
| 6. ACCESSIBILITY TO PUBLIC: | EXTERIOR VISIBLE FROM PUBLIC ROAD | INTERIOR ACCESSIBLE | IF YES, EXPLAIN |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |

DESCRIPTION

| | | | |
|--|---|---|---|
| 7. STYLE OF BUILDING Federal | | DATE OF CONSTRUCTION Jan. 1824 | |
| 8. MATERIAL(S) (Indicate use or location when appropriate) | | | |
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) _____ |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input checked="" type="checkbox"/> 2 chimneys | <input checked="" type="checkbox"/> Fieldstone Foundation |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: _____ | <input type="checkbox"/> Cut stone Type: _____ | |
| 9. STRUCTURAL SYSTEM | | | |
| <input checked="" type="checkbox"/> Wood frame | <input checked="" type="checkbox"/> Post and beam | <input type="checkbox"/> balloon | |
| <input type="checkbox"/> Load bearing masonry | | <input type="checkbox"/> Structural iron or steel | |
| <input checked="" type="checkbox"/> Other (Specify) Plank frame | | | |
| 10. ROOF (Type) | | | |
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ |
| (Material) | | | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) _____ |
| 11. NUMBER OF STORIES 2 1/2 | | APPROXIMATE DIMENSIONS 30' x 45' | |
| 12. CONDITION (Structural) | | | |
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
| 13. INTEGRITY (Location) | | | |
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | WHEN? | (Alterations) <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No IF YES, EXPLAIN West wing rebuilt |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | | |
| <input checked="" type="checkbox"/> Barn | <input checked="" type="checkbox"/> Shed | <input type="checkbox"/> Garage | <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) 2 ponds, brook, mature evergreens at boundaries, hemlock hedges. |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input checked="" type="checkbox"/> Garden | Formal flower garden, veg. garden, fruit trees. corn crib |
| 15. SURROUNDING ENVIRONMENT | | | |
| <input checked="" type="checkbox"/> Open land | <input type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input checked="" type="checkbox"/> Rural | <input type="checkbox"/> High building density |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | | |
| Situated on north side of Old Post Rd., facing south to open farm land between Old Post Rd. and Middletown Ave. | | | |

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

1. Good example of changes to lighter style in early 1800's, but retaining heavy post and beam construction with plank frame, and numerous fireplaces.
2. Delicate, Federal front portico with elliptical arch in pediment. Fanlight over door with narrow side lights.
3. Gable end to road, 2½ stories, with 1½ story wing on west.
4. Central chimney with four fireplaces. Wing Chimney has living-room and cellar fireplaces.
5. Federal style woodwork. (Cont.)

18 ARCHITECT

BUILDER
Thaddeus Maltby

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

1. The date is authenticated by the writing on a siding plank, "Jan. 24, 1824", found when a doorway was cut between the kitchen and dining room.
2. That there was an earlier dwelling on this site was evidenced by the cellar kitchen in wing with working fireplace and the opening out to grade.
3. 1852 County Map shows 11 Maltby houses in the area.

SOURCES

Beers Atlas 1868
County Map 1856
County Map 1852
Lydia S. Davis, owner 1929-1979
W.P.A. Census #47

PHOTOGRAPHER
Ruth Arnold 5/79

VIEW
3/4 Left Front

NEGATIVE ON FILM
yes

COMPILED BY
NAME
Lydia L. Davis 8/78

ORGANIZATION
Totoket Historical Society, Inc

ADDRESS
P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

None known Highways Vandalism Developers Other _____

Renewal Private Deterioration Zoning Explanaton _____

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford, Connecticut 06106
HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

| | | | |
|---------------------|-----------|-----|---------------------|
| FOR OFFICE USE ONLY | | | |
| TOWN NO.: | SITE NO.: | | |
| UTM: 18/ | / | / | / |
| QUAD: | | | |
| DISTRICT: | S | NR: | ACTUAL POTENTIAL |

CONTINUATION SHEET

Item number: 186 Date: _____

Item number 17;

6. Roomy central hall and original oak floors.
7. 5 window front with entrance at left.
8. Cased corner posts.
9. Oval window removed from peak at uncertain date.

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM: | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 187

| | | |
|---|---|---------------------|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | |
| | Cecarelli Farm Harrison | |
| | 2. TOWN CITY | VILLAGE COUNTY |
| | North Branford | Northford New Haven |
| | 3. STREET AND NUMBER (and or location) | |
| | 200 Old Post Road | |
| | 4. OWNER(S) | |
| | Cecarelli Brothers <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | |
| | 5. USE (Present) (Historic) | |
| | Farm Residence Lorenzo Harrison's Store | |
| DESCRIPTION | 6. ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | EXTERIOR VISIBLE FROM PUBLIC ROAD <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | INTERIOR ACCESSIBLE <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
| | IF YES, EXPLAIN | |
| | 7. STYLE OF BUILDING | |
| | Colonial | |
| | DATE OF CONSTRUCTION | |
| | c 1790 | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | |
| | <input checked="" type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input checked="" type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) _____ <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input type="checkbox"/> Fieldstone <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: _____ <input checked="" type="checkbox"/> Cut stone Type: Sandstone - foundations chimney central | |
| 9. STRUCTURAL SYSTEM | | |
| <input checked="" type="checkbox"/> Wood frame <input checked="" type="checkbox"/> Post and beam <input type="checkbox"/> balloon <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____ | | |
| 10. ROOF (Type) | | |
| <input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ (Material) _____ <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ | | |
| 11. NUMBER OF STORIES | | |
| 2 + attic | | |
| APPROXIMATE DIMENSIONS | | |
| 68' x 30' | | |
| 12. CONDITION (Structural) (Exterior) | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| 13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN | | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Wings added to west & north | | |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input checked="" type="checkbox"/> Barn S <input checked="" type="checkbox"/> Shed <input checked="" type="checkbox"/> Garage <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) Modern concrete-block farm buildings <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | |
| 15. SURROUNDING ENVIRONMENT | | |
| <input checked="" type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input checked="" type="checkbox"/> Rural <input type="checkbox"/> High building density | | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| House with barns and out buildings set on hill top in large acreage - North side of road, about 1/2 mile northeast of Northford Center. | | |

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR. SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 188

IDENTIFICATION

1. BUILDING NAME (Common) _____ (Historic)

2. TOWN CITY _____ VILLAGE _____ COUNTY _____
 North Branford Northford New Haven

3. STREET AND NUMBER (and or location)
 145 Old Post Rd.

4. OWNER(S) _____ Public Private
 Michael & Andrea Hogan

5. USE (Present) _____ (Historic)
 Residence Residence

6. ACCESSIBILITY TO PUBLIC: Yes No EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE IF YES, EXPLAIN

DESCRIPTION

7. STYLE OF BUILDING _____ DATE OF CONSTRUCTION _____
 Bungalow 1926

8. MATERIAL(S) (Indicate use or location when appropriate)

| | | | |
|--|---|---|--|
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) _____ |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input type="checkbox"/> Fieldstone | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input checked="" type="checkbox"/> Cobblestone | |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: _____ | <input type="checkbox"/> Cut stone Type: _____ | |

9. STRUCTURAL SYSTEM

| | | |
|--|---|---|
| <input checked="" type="checkbox"/> Wood frame | <input type="checkbox"/> Post and beam | <input checked="" type="checkbox"/> balloon |
| <input type="checkbox"/> Load bearing masonry | <input type="checkbox"/> Structural iron or steel | |
| <input type="checkbox"/> Other (Specify) _____ | | |

10. ROOF (Type)

| | | | | |
|---|-------------------------------|---|----------------------------------|--|
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input checked="" type="checkbox"/> Hip | <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) _____ |

(Material)

| | | | |
|---|---------------------------------------|-------------------------------|--|
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) _____ |

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
 1 + attic 38' x 55'

12. CONDITION (Structural) (Exterior)

| | | | | | | | |
|------------------------------------|--|-------------------------------|---------------------------------------|------------------------------------|--|-------------------------------|---------------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
|------------------------------------|--|-------------------------------|---------------------------------------|------------------------------------|--|-------------------------------|---------------------------------------|

13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN

| | | | |
|--|--------------------------------|------------------------------|-----------------------------|
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | <input type="checkbox"/> Yes | <input type="checkbox"/> No |
|--|--------------------------------|------------------------------|-----------------------------|

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

| | | | |
|---|-------------------------------|--|--|
| <input type="checkbox"/> Barn | <input type="checkbox"/> Shed | <input checked="" type="checkbox"/> Garage | <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) Swimming pool |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden | Fenced horse paddock, Horse stable |

15. SURROUNDING ENVIRONMENT

| | | | |
|---|--------------------------------------|---|---|
| <input checked="" type="checkbox"/> Open land | <input type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input type="checkbox"/> Rural | <input type="checkbox"/> High building density |

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
 Situated on the south east side of Old Post Rd. at intersection with Dayton Hill Rd. House faces small landscaped island formed by intersecting roads. House seems to crouch between large evergreens flank-ing entry.

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

A nice example of the bungalow style made special by the wide hip roofed porch at the front and sides. Main body of house composed of two shallow gabled elements which are given flare at the sides by shallower porch roof. Shed dormer at north. Wing at south contains a complete horizontal band of windows on gable end. Louvered opening centered on front gable. 5 bays at front of porch, 2 bays at sides, square columns with simply scrolled brackets and vertical balusters in railings. Cobblestone piers support porch columns, between which are lattice panels.
Large lot contains pool and paddock.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

On site of Mansfield Tavern.

SOURCES

N. B. Assessor's records

PHOTO

PHOTOGRAPHER

Ruth Arnold

5/79

VIEW

Front

NEGATIVE ON FILE

yes

COMPILED BY

NAME

Lydia Davis

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item #189

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)

2. TOWN CITY VILLAGE COUNTY

North Branford Northford New Haven

3. STREET AND NUMBER (and or location)

133 Old Post Rd.

4. OWNER(S) Public Private

Masonic Charity Foundation of Conn.

5. USE (Present) (Historic)

Residence Residence

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN

Yes No Yes No

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION

Bungalow Cottage c 1900

8. MATERIAL(S) (Indicate use or location when appropriate)

Clapboard Asbestos Siding Brick chimney Other (Specify) _____

Wood Shingle Asphalt Siding Fieldstone

Board & Batten Stucco Cobblestone chimney

Aluminum Siding Concrete Type: _____ Cut stone Type: _____

9. STRUCTURAL SYSTEM

Wood frame Post and beam balloon Structural iron or steel

Load bearing masonry Other (Specify) _____

10. ROOF (Type)

Gable Flat Mansard Monitor sawtooth

Gambrel Shed Hip Round Other (Specify) _____

(Material)

Wood Shingle Roll Asphalt Tin Slate

Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS

1 + attic 28' x 48'

12. CONDITION (Structural) (Exterior)

Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN

On original site Moved Yes No wings to north & east added

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

Barn Shed Garage Other landscape features or buildings (Specify) _____

Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT

Open land Wood-land Residential Scattered buildings visible from site

Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS

On east side of Old Post Rd. at intersection with Dayton Hill Rd.
 Gable end facing road.

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

1. Gable faces road.
2. Entry at center with small, arched, lattice portico. One 6/6 window on each side.
3. Moderately wide roof overhangs.

18 ARCHITECTURE

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Small cottage. Unusual half round fanlight in attic with paired, half round tracery.

SOURCES

Assessor's records

PHOTO

PHOTOGRAPHER

Ruth Arnold

4/79

VIEW

Front

NEGATIVE ON FILE

yes

COMPILED BY

NAME

E. A. Livingston

3/20/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472

20 SUBSEQUENT FIELD EVALUATIONS



21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
- Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 190

IDENTIFICATION

1. BUILDING NAME (Common) _____ (Historic)

2. TOWN CITY _____ VILLAGE _____ COUNTY _____
 North Branford Northford New Haven

3. STREET AND NUMBER (and or location)
 61 Old Post Rd.

4. OWNER(S) _____ Public Private
 DeWitt T. & Bruce A. Williams

5. USE (Present) _____ (Historic)
 Residence Residence

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN

DESCRIPTION

7. STYLE OF BUILDING _____ DATE OF CONSTRUCTION _____
 Simplified Greek Revival c. 1860

8. MATERIAL(S) (Indicate use or location when appropriate)
 Clapboard Asbestos Siding Brick Other (Specify) cinder block-partial foundation
 Wood Shingle Asphalt Siding Fieldstone chimney foundation
 Board & Batten Stucco Cobblestone foundation
 Aluminum Siding Concrete Type: under ell Cut stone Type: Sandstone foundation

9. STRUCTURAL SYSTEM
 Wood frame Post and beam balloon Structural iron or steel
 Load bearing masonry Other (Specify) _____

10. ROOF (Type)
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify) _____
 (Material)
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES _____ APPROXIMATE DIMENSIONS _____
 1 1/2 33' x 29'

12. CONDITION (Structural) _____ (Exterior) _____
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) _____ WHEN? _____ (Alterations) _____ IF YES, EXPLAIN _____
 On original site Moved Yes No very much rebuilt

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify)
 Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
 Sited very close to road on east side almost opposite Pistapoug Rd.
 Land slopes steeply to rear exposing basement level.

(OVER)

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

1. Two front doors-one at each end of facade. Windows asymmetrical - 2 at south door, 1 at north.
2. Modern window sash 2/2 (horizontal muntin). One gable window at south.
3. Rear portion of house flared out with shallower roof pitch.
4. Small, modern ell to south.
5. Hip roof front porch continuous from end to end. Small, vertical board infill at railings and valance.

SIGNIFICANCE

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

Probably built by one of the Williams family who owned much property in the area.

SOURCES

Assessor's records 67-59
Beers Atlas 1868-(unnamed)

PHOTO
COMPILED BY

PHOTOGRAPHER

Ruth Arnold

4/79

VIEW

Front

NEGATIVE ON FILE

yes

NAME

Janet S. Gegan


3/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

Item # **292**

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

| | | | | |
|--|--|---|--|--|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | | Philo Williams | |
| | 2 TOWN CITY | VILLAGE | COUNTY | |
| | North Branford | Northford | New Haven | |
| | 3 STREET AND NUMBER (and or location) Old Post Rd. | | | |
| | 4. OWNER(S) Thomas C & Marianne B. Smith <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | | | |
| | 5 USE (Present) | | (Historic) | |
| | Residence | | Residence | |
| | 6 ACCESSIBILITY TO PUBLIC: | EXTERIOR VISIBLE FROM PUBLIC ROAD | INTERIOR ACCESSIBLE | IF YES, EXPLAIN |
| | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | |
| | 7. STYLE OF BUILDING Late Greek Revival | | | DATE OF CONSTRUCTION .c. 1860 |
| DESCRIPTION | 8 MATERIAL(S) (Indicate use or location when appropriate) | | | |
| | <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick chimney | <input type="checkbox"/> Other (Specify) |
| | <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input type="checkbox"/> Fieldstone | |
| | <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | |
| | <input checked="" type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: | <input checked="" type="checkbox"/> Cut stone Type: Sandstone foundation | |
| | 9 STRUCTURAL SYSTEM | | | |
| | <input checked="" type="checkbox"/> Wood frame | <input type="checkbox"/> Post and beam | <input checked="" type="checkbox"/> balloon | |
| | <input type="checkbox"/> Load bearing masonry | | <input type="checkbox"/> Structural iron or steel | |
| | <input type="checkbox"/> Other (Specify) | | | |
| | 10 ROOF (Type) | | | |
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) | |
| (Material) | | | | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) | |
| 11 NUMBER OF STORIES | APPROXIMATE DIMENSIONS | | | |
| 2 | 30' x 45' | | | |
| 12 CONDITION (Structural) | | (Exterior) | | |
| <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | |
| <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | |
| 13 INTEGRITY (Location) | | WHEN ? | (Alterations) IF YES, EXPLAIN | |
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No wing & porch added | |
| 14 RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | | | |
| <input checked="" type="checkbox"/> Barn | <input type="checkbox"/> Shed | <input checked="" type="checkbox"/> Garage | <input type="checkbox"/> Other landscape features or buildings (Specify) | |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden | | |
| 15 SURROUNDING ENVIRONMENT | | | | |
| <input checked="" type="checkbox"/> Open land | <input type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site | |
| <input checked="" type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input type="checkbox"/> Rural | <input type="checkbox"/> High building density | |
| 16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | | | |
| Sited on east side of road. Land drops off steeply to rear so back is three stories. Former school bus barn is to south. | | | | |

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

DESCRIPTION (Continued)

Main east-west element has 2 stories, shallow pitch roof, approx. 1' overhangs, no cornice returns and 2 bay, 4 window front. South wing has 1½ stories, also shallow pitch roof. Main entrance is at front of south wing. Gable end of south wing has pair of tall narrow windows at 1st floor. Windows 1/1, not original. Glassed in porch at entry.

18 ARCHITECT

BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Formerly belonged to Clarence & Eleanor Williams. He operated the school bus company that served the town for many years. The 34' x 44' bus barn is to the south.

SOURCES

Assessor's Records 67-60
Elizabeth Livingston

PHOTO
COMPILED BY

PHOTOGRAPHER

Ruth Arnold

6/79

VIEW

Front

NEGATIVE ON FILM

yes

NAME

Janet S. Gegan

3/80

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 192

| | | |
|---|--|----------------------|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) Benjamin Howd | |
| | 2 TOWN CITY North Branford | VILLAGE Northford |
| | 3 STREET AND NUMBER (and or location) 58 Old Post Road | |
| | 4. OWNER(S) Henry Jakubisyn <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | |
| | 5 USE (Present) (Historic) Residence Residence | |
| | 6 ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | EXTERIOR VISIBLE FROM PUBLIC ROAD <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | INTERIOR ACCESSIBLE <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
| | IF YES, EXPLAIN | |
| | 7 STYLE OF BUILDING Colonial - Integral Saltbox | |
| DATE OF CONSTRUCTION c.1740 | | |
| DESCRIPTION | 8 MATERIAL(S) (Indicate use or location when appropriate) | |
| | <input type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input checked="" type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) _____ | |
| | <input checked="" type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input checked="" type="checkbox"/> Fieldstone chimneys foundation | |
| | <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone | |
| | <input type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: _____ <input type="checkbox"/> Cut stone Type: _____ | |
| | 9 STRUCTURAL SYSTEM | |
| | <input checked="" type="checkbox"/> Wood frame <input checked="" type="checkbox"/> Post and beam <input type="checkbox"/> balloon | |
| | <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel | |
| | <input type="checkbox"/> Other (Specify) _____ | |
| | 10 ROOF (Type) | |
| <input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth | | |
| <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input checked="" type="checkbox"/> Other (Specify) See 17 | | |
| (Material) | | |
| <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate | | |
| <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ | | |
| 11 NUMBER OF STORIES APPROXIMATE DIMENSIONS | | |
| 2 + attic 34' X 16' + ell 38' X 18' + shed | | |
| 12 CONDITION (Structural) (Exterior) | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| 13 INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN | | |
| <input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Many small alterations and additions over the years. | | |
| 14 RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input type="checkbox"/> Barn <input checked="" type="checkbox"/> Shed <input checked="" type="checkbox"/> Garage <input type="checkbox"/> Other landscape features or buildings (Specify) attached | | |
| <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | |
| 15 SURROUNDING ENVIRONMENT | | |
| <input checked="" type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input checked="" type="checkbox"/> Scattered buildings visible from site | | |
| <input type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial <input type="checkbox"/> Rural <input type="checkbox"/> High building density | | |
| 16 INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| West side of Old Post Road facing east. On open land sloping up to west, between Pistapaug Road and W. A. Douglas School. | | |

(OVER)

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

3-bay facade, 1/1 windows throughout except for 6/6 attic gable windows and 3 second story 6/6 windows on south of ell. Large center chimney steeply sloping roof in integral saltbox configuration. Strong, molded front cornice. Long, rear ell has shallow single slope roof at south and gambrel roof with 2 shed dormers at north. Shed attached at rear of ell to west and modern enclosed entrance at south.

Ell was probably built prior to 1760.

The combination of varied shapes in this structure is of interest.

18 ARCHITECT

BUILDER
Benjamin Howd

SIGNIFICANCE

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

Of the three Benjamin Howds, Benjamin II (1708-1750) probably built this house on his father's land. It was bequeathed to him in a will dated 1740 as "all Houseing & Lands up Stoney River where he now dwells." (He also was left 1/2 the carpenter's tools). Benjamin I (d. 1749) is probably the one to whom Mrs. Morris Alling attributed the Sol's Path house.

In 1763 James Howd, the son of Benjamin II, sold for \$5 to the Episcopal Church of England 18 square rod (c.1/9 acre) on the south end of his house lot. The church (30' X 24') was built there in 1764, and remained at that site until 1845 when a new church was built further south. The building was later turned into a barn, which stood until the mid-1900's.

SOURCES

County Maps 1852 & 1856. Jean C. Alling, A Silent Witness, 93
 Beers Atlas 1868.
 Guilford Probate Court Records - Vol. IV:
 536 - October 3, 1749; Vol. V:200,
 Nov. 7, 1752.
 Branford Land Records, Vol. 8:280 et al.

PHOTO

PHOTOGRAPHER
Robert Van Nest 1977

VIEW
3/4 Front - south


NEGATIVE O
Yes

COMPILED BY

NAME
Lydia L. Davis

ORGANIZATION
Totoket Historical Society, Inc.

ADDRESS
P.O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

None known Highways Vandalism Developers Other _____

Renewal Private Deterioration Zoning Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

FOR OFFICE USE ONLY

Town No.: _____ Site No.: _____

UTM: | | | | | | | | | | | | | | | | | | | | | |

QUAD: _____

DISTRICT: S NR IF NR SPECIFY: Actual Potential

Item # 193

| | | |
|--|---|-----------|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | |
| | William Douglas School | |
| | 2. TOWN CITY | VILLAGE |
| | North Branford | Northford |
| | 3. STREET AND NUMBER (and or location) | |
| | Old Post Road (1/2 mile north of green) | |
| | 4. OWNER(S) | |
| | Town of North Branford <input type="checkbox"/> Public <input type="checkbox"/> Private | |
| | 5. USE (Present) (Historic) | |
| | School-grades 1 & 2 Elementary School | |
| DESCRIPTION | 6. ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | EXTERIOR VISIBLE FROM PUBLIC ROAD <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | INTERIOR ACCESSIBLE <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | IF YES, EXPLAIN Elementary School-Public Building | |
| | 7. STYLE OF BUILDING | |
| | Classic Revival | |
| | DATE OF CONSTRUCTION | |
| | 1924-1952-1960 | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | |
| | <input checked="" type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input checked="" type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) foundations & additions <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input type="checkbox"/> Fieldstone <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: _____ <input type="checkbox"/> Cut stone Type: _____ | |
| 9. STRUCTURAL SYSTEM | | |
| <input checked="" type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input type="checkbox"/> balloon <input checked="" type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____ | | |
| 10. ROOF (Type) | | |
| <input type="checkbox"/> Gable <input checked="" type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ (Material) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ | | |
| 11. NUMBER OF STORIES | | |
| 1 | | |
| APPROXIMATE DIMENSIONS | | |
| 213' x 76' (orig. 89' x 54') | | |
| 12. CONDITION (Structural) (Exterior) | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| 13. INTEGRITY (Location) | | |
| <input type="checkbox"/> On original site <input type="checkbox"/> Moved <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No IF YES, EXPLAIN Extensive additions on north & south | | |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) Playground, Parking lot on north, concrete retaining wall at front <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | |
| 15. SURROUNDING ENVIRONMENT | | |
| <input checked="" type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input checked="" type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Indus-trial <input type="checkbox"/> Rural <input type="checkbox"/> High building density | | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| Sited west side of road on hill facing east, well back from road. Open land opposite allows view of Totoket Ridge. | | |

(OVER)


17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)
 DESCRIPTION (Continued)
 Original 1924 clapboard building at center of two undistinguished additions. A crisp classical design with a large, arched, central doorway enclosure recessed into facade. Arch topped with large scroll key that penetrates frieze under cornice. Double doors are surrounded by heavy molding and flanked by smooth columns with Ionic capitals. Atop entry cornice sit 2 black painted eagles, over columns. Above, within the panelled, arched recess is situated a leaded half round window with a delicate radial configuration. 4 round headed, tall, classroom windows are located on each side of the center entry. These are 19/12 sash also with a radial configuration at the heads. Simple board trimmed windows with tall keys are linked to one another at base of arches by labels. Strong, quoins at corners. Roof cornice composed of heavy frieze board, egg and dart mold, sawn fret mold, and plain mutule blocks under strongly projecting cornice.

18 ARCHITECT BUILDER

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE
 SIGNIFICANCE
 Built as a four room school in 1924 to replace the one room schools in Northford. Cost \$22,000. A cafeteria-assembly room was added to north end and classrooms were added, as needed, to the south. Playground area is rear and north. It is on the site of the District #6 School. Northford Villiage Improvement Society took over old school, used it as a community house until they built a new one in 1927. This building was removed in 1952 to allow for parking area. Original site of St. Andrew's Episcopal Church was located just north (playground area). A stone commemorates the spot.

SOURCES
 North Branford Town Meeting Minutes of 1922-1927.
 Lydia Davis
 Helen Livingston
 Assessor's Records

PHOTO
 PHOTOGRAPHER Ruth Arnold 5/79
 VIEW Front NEGATIVE ON FIL yes
 COMPILED BY
 NAME Lydia L. Davis 10/79
 ORGANIZATION Totoket Historical Society, Inc.
 ADDRESS P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

None knowr Highways Vandalism Developers Other _____

Renewal Private Deterloration Zoning Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item #194

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
 Congregational Church Parish House | Thomas A. Smith

2. TOWN CITY | VILLAGE | COUNTY
 North Branford | Northford | New Haven

3. STREET AND NUMBER (and or location)
 14 Old Post Rd.

4. OWNER(S)
 Northford Congregational Church, U. C. C. Public Private

5. USE (Present) (Historic)
 Sunday School, Church Activities | Residence

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN
 Meetings, etc. & by request

DESCRIPTION

7. STYLE OF BUILDING | DATE OF CONSTRUCTION
 Victorian, late Greek Revival | c. 1860

8. MATERIAL(S) (Indicate use or location when appropriate)
 Clapboard Asbestos Siding Brick Other chimney (Specify)
 Wood Shingle Asphalt Siding Fieldstone
 Board & Batten Stucco Cobblestone
 Aluminum Siding Concrete Type: Cut stone red sandstone - foundation Type:

9. STRUCTURAL SYSTEM
 Wood frame Post and beam balloon Structural iron or steel
 Load bearing masonry Other (Specify)

10. ROOF (Type) (Material)
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify)
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify)

11. NUMBER OF STORIES | APPROXIMATE DIMENSIONS
 2 1/2 | 30' x 62' (Main house 24'3" x 30'4")

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated | Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN
 On original site Moved Yes No

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify)
 Sandstone terrace wall at front. Row of 10 maple trees on street.
 Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
 On west, set back 84' and high above road. Large lawn area slopes down to south towards Congregational Church. Old stone pasture wall at rear. Lawn slopes up to north towards William Douglas School. Sandstone terrace wall at front merges into stone pasture wall to north. (OVER)

Drive curves in and out.

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

1. Gable end to road, facing east, with 5 window front & door to left. Gable contains small horizontal window.
2. One story ell in two steps at rear (west).
3. Windows are 6/6 or 2/2.
4. Two story bay window on south side, possibly added later.
5. Typical Victorian interior floor plan.
6. "Comb" painting on doors, now painted white. Coarse woodwork. Cherry stair rail.

SIGNIFICANCE

18 ARCHITECT

BUILDER

By/for Thomas A. Smith

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

1. Thomas A. Smith (1827-1902), son of Thomas and Hannah (Tuttle) Smith was in the manufacturing business in Northford. After 1875, he was a merchant. He also served as postmaster for 12 years when the card business was flourishing in Northford - a second class post office in 1888. Also, he was a representative to the Conn. Legislature.
2. Stanley A. Williams lived here earlier this century. He was very active in community affairs. Stanley T. Williams School is named after him.

SOURCES

Beers Atlas 1868
 Mrs. Morris Allings Notes - THS files.
 Assessors records 67-8

PHOTO

PHOTOGRAPHER

Ruth Arnold

4/79

VIEW

Front

NEGATIVE ON FILE

yes

COMPILED BY

NAME

Lydia L. Davis

10/14/79

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT. 06472



21 THREATS TO BUILDING OR SITE

- None known Highways Vandalism Developers Other _____
- Renewal Private Deterioration Zoning Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # **195**

| | | |
|---|--|-----------------------|
| IDENTIFICATION | 1. BUILDING NAME (Common) (Historic) | |
| | Little Red School House | District no. 4 School |
| | 2. TOWN CITY | VILLAGE COUNTY |
| | North Branford | Northford New Haven |
| | 3. STREET AND NUMBER (and or location) | |
| | Old Post Rd. (500' from Northford Green, east side of road) | |
| | 4. OWNER(S) | |
| | The Northford Congregational Church <input checked="" type="checkbox"/> Public <input type="checkbox"/> Private | |
| | 5. USE (Present) (Historic) | |
| | Museum - not open on a regular basis District 4 School | |
| DESCRIPTION | 6. ACCESSIBILITY TO PUBLIC: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | |
| | EXTERIOR VISIBLE FROM PUBLIC ROAD INTERIOR ACCESSIBLE IF YES, EXPLAIN | |
| | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No By appointment with Historical S. | |
| | 7. STYLE OF BUILDING | |
| | Simplified Federal | |
| | DATE OF CONSTRUCTION | |
| | c. 1805 | |
| | 8. MATERIAL(S) (Indicate use or location when appropriate) | |
| | <input checked="" type="checkbox"/> Clapboard red <input type="checkbox"/> Asbestos Siding <input type="checkbox"/> Brick <input checked="" type="checkbox"/> Other (Specify) <u>chimney</u> <input checked="" type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input type="checkbox"/> Fieldstone <u>Rough laid sandstone foundations</u> <input checked="" type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: _____ <input type="checkbox"/> Cut stone Type: _____ <input checked="" type="checkbox"/> doors & shutters | |
| | 9. STRUCTURAL SYSTEM | |
| <input checked="" type="checkbox"/> Wood frame <input checked="" type="checkbox"/> Post and beam <input type="checkbox"/> balloon <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____ | | |
| 10. ROOF (Type) | | |
| <input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ (Material) <input checked="" type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ | | |
| 11. NUMBER OF STORIES APPROXIMATE DIMENSIONS | | |
| 1 16' x 24' | | |
| 12. CONDITION (Structural) (Exterior) | | |
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated | | |
| 13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN | | |
| <input type="checkbox"/> On original site <input checked="" type="checkbox"/> Moved 1928 <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | |
| <input type="checkbox"/> Barn <input type="checkbox"/> Shed <input type="checkbox"/> Garage <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) Brick path, lilac trus <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden | | |
| 15. SURROUNDING ENVIRONMENT | | |
| <input checked="" type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input checked="" type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Rural <input type="checkbox"/> High building density | | |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | |
| School house located on east side of road 24' back, next to Congregational Parsonage, and across street from the Church and Parish House. | | |

(OVER)

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR. SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 196

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
 Northford Congregational Church "Stone Meeting House"

2. TOWN CITY VILLAGE COUNTY
 North Branford Northford New Haven

3. STREET AND NUMBER (and or location)
 4 Old Post Road

4. OWNER(S) (United Church of Christ) Public Private
 Members of Northford Congregational Church

5. USE (Present) (Historic)
 Religious services, Community Meet. Worship and Meeting House

6. ACCESSIBILITY TO PUBLIC: Yes No EXTERIOR VISIBLE FROM PUBLIC ROAD
 Yes No INTERIOR ACCESSIBLE IF YES, EXPLAIN
 Public House of Worship

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
 Gothic Revival 1845

8. MATERIAL(S) (Indicate use or location when appropriate)
 Clapboard Asbestos Siding Brick Other (Specify)
 Wood Shingle Asphalt Siding Fieldstone
 Board & Batten Stucco Cobblestone Local sandstone foundations, super structure, steps, walks
 Aluminum Siding Concrete Type: Cut stone Type:

9. STRUCTURAL SYSTEM
 Wood frame Post and beam balloon
 Load bearing masonry Structural iron or steel Steel beams under first floor.
 Other (Specify)

10. ROOF (Type)
 Gable steep Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify)
 (Material)
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify)

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
 2 stories 58' x 40'

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN? (Alterations) IF YES, EXPLAIN
 On original site Moved Yes No New roof structure. Basement modernized for community use.

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify)
 Carriage house Shop Garden Large parking lot on north. Evergreen foundation planting

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Industrial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
 Splendid location on elevated corner above the village. At corner of Old Post Rd. and Clintonville Rd. Church faces east.

(OVER)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

Random ashlar sandstone throughout. Buttresses with weatherings and pointed terminals on three corners, bell tower on fourth. Pointed arched main side windows contain wood muntins, diamond panes and are topped with hood molding. At front, the central rectangular entry and central, pointed arched window are separated by a belt course. Both have hood molding with shield-like label stops. The center, wood, double leaf doors each contain 8 panels and are topped as a shallow, four-centered pointed arch. Rectangular, hooded window at right. Center window contains a form of intersecting tracery with leaded glass infill. Tower at southeast has diagonal, weathered buttresses on all exposed corners, single pointed arch windows on first floor facades, with paired keyhole type windows at second level topped by round wheel windows. The present wood belfry differs considerably

18 ARCHITECT

Henry Austin

BUILDER (Cont.)

George Perry, master builder & Mr. Merriman, master joiner, Mr. Larkin, master mason.

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE

Before the fire of 1906, the church contained balconies along 2 sides. It now has a roomy balcony at the rear accommodating the organ. Present beam and panel ceiling replaces an earlier more medieval structure of Cherry. The church as it stands was dedicated in 1908. Organized in 1750 with 19 members. Date stone on tower - 1846

SOURCES

Beers Atlas 1868
 County Map 1856
 County Map 1852
 Official Church Records

PHOTOGRAPHER

Ruth Arnold 4/79

VIEW

Front

NEGATIVE ON FILE

yes

COMPILED BY


Lydia L. Davis 9/79

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

None known Highways Vandalism Developers Other _____

Renewal Private Deterloration Zoning Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM: | |
| QUAD: | |
| DISTRICT | IF NR. SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 197

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
Edward Smith Memorial Library

2. TOWN CITY VILLAGE COUNTY
North Branford Northford New Haven

3. STREET AND NUMBER (and/or location)
At intersection of Middletown Trnpg. & Old Post Rd. - Entrance on Old Post

4. OWNER(S)
Town of North Branford Public Private

5. USE (Present) (Historic)
Public Library

6. ACCESSIBILITY TO PUBLIC: Yes No EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN
Public building

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
Colonial Revival*Georgian .1956 & 1965

8. MATERIAL(S) (Indicate use or location when appropriate)
 Clapboard Asbestos Siding Brick Other (Specify) Cement block
 Wood Shingle Asphalt Siding Veneer Fieldstone
 Board & Batten Stucco Cobblestone
 Aluminum Siding Concrete Type: foundation Cut stone Type: _____

9. STRUCTURAL SYSTEM
 Wood frame Post and beam balloon
 Load bearing masonry Original Building Structural iron or steel
 Other (Specify) _____

10. ROOF (Type)
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify) _____
 (Material)
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
1 1/2 38' x 28' original, addition 32' x 44' with basement.

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN
 On original site Moved Yes No Large addition in 1965

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify)
 Carriage house Shop Garden Sign - overgrown foundation planting.

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Industrial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
Sited on point of land above Northford Green, Commanding view of the village to the south. Opposite the Northford Congregational Church.

(OVER)

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

An L shaped building set on the point of land between two highways at a considerable elevation. Three chimneys, brick with white trim. Over planted at foundation. Entrance on Old Post Road. This steep highway bank has been planted with spreading juniper by the Northford Garden Club.

SIGNIFICANCE

18 ARCHITECT

BUILDER

1. Everett Bradley 2. Harvey Babbitt

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

In 1938, Clara E. Smith left her estate to the Town of North Branford for the building of a public library in Northford, to be called The Edward Smith Library in memory of her father. In 1956, the town erected a small brick building (architect - Bradley) which was soon outgrown. In 1965, the building was remodeled and enlarged to accommodate a childrens' dept. in the basement and the original first floor space is now used as a reference room.

SOURCES

Town Meeting Minutes.
Lydia Davis recollections. - THS

PHOTO

PHOTOGRAPHER

Ruth Arnold 4/79

VIEW

Rear - Entrance

NEGATIVE ON FILE

yes

COMPILED BY

NAME

Lydia Davis 10/79

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT. 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
- Highways
- Vandalism
- Developers
- Other _____
- Renewal
- Private
- Deterloration
- Zoning
- Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES

HIST-6 NEW 5 77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION

59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

Item # **198**

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM: | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

IDENTIFICATION

1. BUILDING NAME (Common) *(Historic)*
Pine Hollow Subdivision

2. TOWN CITY **North Branford** VILLAGE _____ COUNTY **New Haven**

3. STREET AND NUMBER (and/or location)
14, 15, 18, 21, 24, 30 Pine Hollow Road

4. OWNER(S) **14-Johnston, 15-Manniel, 18-Pais, 21-Normandin, 24-Libby, 30-Sorrentino** Public Private

5. USE (Present) *(Historic)*
Residential

6. ACCESSIBILITY TO PUBLIC: EXTERIOR VISIBLE FROM PUBLIC ROAD Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN _____

DESCRIPTION

7. STYLE OF BUILDING **Modern** DATE OF CONSTRUCTION **1976-78**

8. MATERIAL(S) (Indicate use or location when appropriate)

| | | | |
|--|---|--|---|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input checked="" type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) vertical rough sawn eastern pine. |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Siding | <input type="checkbox"/> Chimneys | <input type="checkbox"/> Fieldstone |
| <input checked="" type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | |
| <input type="checkbox"/> Aluminum Siding | <input checked="" type="checkbox"/> Concrete Type: poured foundation | <input type="checkbox"/> Cut stone Type: _____ | |

9. STRUCTURAL SYSTEM

| | | |
|--|---|---|
| <input checked="" type="checkbox"/> Wood frame | <input type="checkbox"/> Post and beam | <input checked="" type="checkbox"/> balloon |
| <input type="checkbox"/> Load bearing masonry | <input type="checkbox"/> Structural iron or steel | |
| <input type="checkbox"/> Other (Specify) _____ | | |

10. ROOF (Type)

| | | | | |
|---|--|----------------------------------|--|--|
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor | <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input checked="" type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round | <input type="checkbox"/> Other (Specify) _____ |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate | |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) _____ | |

11. NUMBER OF STORIES **multi level** APPROXIMATE DIMENSIONS **3 max. Vary - large houses by tract development standards.**

12. CONDITION (Structural) *(Exterior)*

| | | | | | | | |
|---|-------------------------------|-------------------------------|---------------------------------------|---|-------------------------------|-------------------------------|---------------------------------------|
| <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated | <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
|---|-------------------------------|-------------------------------|---------------------------------------|---|-------------------------------|-------------------------------|---------------------------------------|

13. INTEGRITY (Location) *(Alterations)* IF YES, EXPLAIN

| | | | | | |
|--|--------------------------------|-------------|---|-----------------------------|---|
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | WHEN? _____ | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | Additions, i.e., south wing Sorrantino |
|--|--------------------------------|-------------|---|-----------------------------|---|

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES

| | | | |
|---|-------------------------------|--|---|
| <input type="checkbox"/> Barn | <input type="checkbox"/> Shed | <input checked="" type="checkbox"/> Garage | <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) Garden walls |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden | |

15. SURROUNDING ENVIRONMENT

| | | | |
|-------------------------------------|---|---|---|
| <input type="checkbox"/> Open land | <input checked="" type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input type="checkbox"/> Rural | <input type="checkbox"/> High building density |

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS

Pine Hollow Rd. connects at a right angle on the south side of Valley Rd. and ends in a cul-de-sac. There are 10 houses, 6 of which were built by Stanley Page: 5 of the 6 are of modern design. The houses are set (OVER)

well back from the road w many existing trees left standing.

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)

DESCRIPTION (Continued)

The quality of design in this, otherwise typical, developers subdivision, is quite high in comparison with other subdivisions in this 1980 survey area. The houses, while employing such design elements of modern architecture as glass window walls, cantilivered decks, large wall surfaces without ornament, two story spaces, etc., have a somewhat rustic quality appropriate to their wooded setting.

18 ARCHITECT



BUILDER

Adapted from Magazine plans by build.

Stanley Page - Guilford

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

SIGNIFICANCE



SOURCES

Laura Page - Stanley Page, Builder
63 Whitfield Street, Guilford




PHOTO

| | | |
|--------------|-------------|-------------------------|
| PHOTOGRAPHER | Ruth Arnold | 11/79 |
| VIEW | Various | NEGATIVE ON FILE yes |

COMPILED BY

| | | |
|--------------|------------------------------------|---------|
| NAME | Frank Pannenberg | 3/26/80 |
| ORGANIZATION | Totoket Historical Society, Inc. | |
| ADDRESS | P. O. Box 117, Northford, CT 06472 | |



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- | | | | |
|--|-----------------------------------|--|---------------------------------|
| <input checked="" type="checkbox"/> None known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Develo |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Zoning |

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

Item # 199

IDENTIFICATION

DESCRIPTION

| | | | |
|--|---|---|--|
| 1. BUILDING NAME (Common) (Historic) | | Captain Stephen Smith | |
| 2. TOWN CITY | VILLAGE | COUNTY | |
| North Branford | Northford | New Haven | |
| 3. STREET AND NUMBER (and or location) | | | |
| 2 Pistapaug Rd. | | | |
| 4. OWNER(S) | | | |
| Peter D. Esposito <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private | | | |
| 5. USE (Present) (Historic) | | Residential | |
| 6. ACCESSIBILITY TO PUBLIC: | | EXTERIOR VISIBLE FROM PUBLIC ROAD | |
| <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | |
| 7. STYLE OF BUILDING | | DATE OF CONSTRUCTION | |
| Central Chimney Colonial | | c. 1760 | |
| 8. MATERIAL(S) (Indicate use or location when appropriate) | | | |
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Asbestos Siding | <input type="checkbox"/> Brick | <input type="checkbox"/> Other (Specify) |
| <input type="checkbox"/> Wood Shingle | <input checked="" type="checkbox"/> Asphalt Siding over clapboard | <input type="checkbox"/> Fieldstone | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Stucco | <input type="checkbox"/> Cobblestone | |
| <input type="checkbox"/> Aluminum Siding | <input type="checkbox"/> Concrete Type: _____ | <input checked="" type="checkbox"/> Cut stone Type: Block sandstone foundation. | |
| 9. STRUCTURAL SYSTEM | | | |
| <input checked="" type="checkbox"/> Wood frame | <input checked="" type="checkbox"/> Post and beam | <input type="checkbox"/> balloon | |
| <input type="checkbox"/> Load bearing masonry | | <input type="checkbox"/> Structural iron or steel | |
| <input type="checkbox"/> Other (Specify) | _____ | | |
| 10. ROOF (Type) | | | |
| <input checked="" type="checkbox"/> Gable | <input type="checkbox"/> Flat | <input type="checkbox"/> Mansard | <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Shed | <input type="checkbox"/> Hip | <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) |
| (Material) | | | |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Roll Asphalt | <input type="checkbox"/> Tin | <input type="checkbox"/> Slate |
| <input checked="" type="checkbox"/> Asphalt shingle | <input type="checkbox"/> Built up | <input type="checkbox"/> Tile | <input type="checkbox"/> Other (Specify) |
| 11. NUMBER OF STORIES | | APPROXIMATE DIMENSIONS | |
| 2 + attic | | 38' x 28' + 15' x 26' addition | |
| 12. CONDITION (Structural) | | (Exterior) | |
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Deteriorated |
| 13. INTEGRITY (Location) | | WHEN ? | (Alterations) IF YES EXPLAIN |
| <input checked="" type="checkbox"/> On original site | <input type="checkbox"/> Moved | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Addition - see #17 |
| 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES | | | |
| <input type="checkbox"/> Barn | <input checked="" type="checkbox"/> Shed | <input checked="" type="checkbox"/> Garage | <input checked="" type="checkbox"/> Other landscape features or buildings (Specify) |
| | | | Corn crib, open wood shed |
| <input type="checkbox"/> Carriage house | <input type="checkbox"/> Shop | <input type="checkbox"/> Garden | |
| 15. SURROUNDING ENVIRONMENT | | | |
| <input checked="" type="checkbox"/> Open land | <input type="checkbox"/> Wood-land | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Scattered buildings visible from site |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Indus-trial | <input checked="" type="checkbox"/> Rural | <input type="checkbox"/> High building density |
| 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS | | | |
| The house is situated on the north side of the road. The back of the house is host to spectacular scenery of gently sloping farm land with rolling hills in the distance, but sold for development. Large cow (OVER) | | | |

Barn to east of house torn down about 1773.

DESCRIPTION (Continued)

17 OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and or exterior)

1. Interior has been well-preserved.
2. 3 fireplaces on first floor. Each displays examples of dentil molding in mantel pieces.
3. Corner cupboard in s. w. corner of house.
4. An oven is found in what was originally the kitchen-dining room.
5. Matched paneling can be found in the enclosed stairwell leading upstairs.
6. One upstairs room has raised panels in the wainscoating.
7. A windlass of tremendous size is in attic. It could have been used to raise cattle during slaughter in an earlier time and used certainly in a different place.
8. The large kitchen ell added prior to 1900 was a small barn or similar structure and has slightly arching corner posts on the (Cont.)

18 ARCHITECT

BUILDER

SIGNIFICANCE

19 HISTORICAL OR ARCHITECTURAL IMPORTANCE

Captain Stephen Smith (1751-1851) served in the U. S. Navy in the Revolution, and died at age 100; the oldest person to have been buried in the Northford Cemetery.

SOURCES

County Maps 1852 & 1856
Beers Map 1868
WPA Records
Elizabeth Livingston, T.H.S.

PHOTO

PHOTOGRAPHER

Robert Van Nest

1977

VIEW

North - front

NEGATIVE ON FILM

COMPILED BY

NAME

Karen Cebula


8/15/79

ORGANIZATION

Totoket Historical Society, Inc.

ADDRESS

P. O. Box 117, Northford, CT 06472



20 SUBSEQUENT FIELD EVALUATIONS

21 THREATS TO BUILDING OR SITE

- None known
 Highways
 Vandalism
 Developers
 Other _____
 Renewal
 Private
 Deterioration
 Zoning
 Explanation _____

HISTORIC RESOURCES INVENTORY
BUILDING AND STRUCTURES
 HIST-6 NEW 5 77

STATE OF CONNECTICUT
 CONNECTICUT HISTORICAL COMMISSION
 59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
 (203) 566-3005

tem # 200

| | |
|--|--|
| FOR OFFICE USE ONLY | |
| Town No.: | Site No.: |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

IDENTIFICATION

1. BUILDING NAME (Common) (Historic)
3 Trap Rock Bungalows

2. TOWN CITY VILLAGE COUNTY
North Branford **North Branford** **New Haven**

3. STREET AND NUMBER (and or location)
Quarry Road (No numbers)

4. OWNER(S)
Tilcon - Tomasso Public Private

5. USE (Present) (Historic)
Residences **Residences**

6. ACCESSIBILITY TO PUBLIC: Yes No INTERIOR ACCESSIBLE Yes No IF YES, EXPLAIN

DESCRIPTION

7. STYLE OF BUILDING DATE OF CONSTRUCTION
Bungalow **1919**

8. MATERIAL(S) (Indicate use or location when appropriate)

Clapboard Asbestos Siding **Chimneys** Other (Specify) _____
 Wood Shingle Asphalt Siding Fieldstone
 Board & Batten Stucco Cobblestone
 Aluminum Siding Concrete Type: **Foundations Poured** Cut stone Type: _____

9. STRUCTURAL SYSTEM
 Wood frame Post and beam balloon
 Load bearing masonry Structural iron or steel
 Other (Specify) _____

10. ROOF (Type)
 Gable Flat Mansard Monitor sawtooth
 Gambrel Shed Hip Round Other (Specify) _____
 (Material)
 Wood Shingle Roll Asphalt Tin Slate
 Asphalt shingle Built up Tile Other (Specify) _____

11. NUMBER OF STORIES APPROXIMATE DIMENSIONS
2 **Row of 3 identical houses - 28½° N.S. X 24½° E.W., 25½° apart.**

12. CONDITION (Structural) (Exterior)
 Excellent Good Fair Deteriorated Excellent Good Fair Deteriorated

13. INTEGRITY (Location) WHEN ? (Alterations) IF YES, EXPLAIN
 On original site Moved Yes No

14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES
 Barn Shed Garage Other landscape features or buildings (Specify) _____
 Carriage house Shop Garden

15. SURROUNDING ENVIRONMENT
 Open land Wood-land Residential Scattered buildings visible from site
 Commercial Indus-trial Rural High building density

16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS
100' north of the intersection of Rt. 80 and Rt. 22 on small dead-end road - Quarry Road. Houses situated on north side of road, set back 30°. Substantial trees along curb area.

(OVER)

